JOINT LEGISLATIVE & EXECUTIVE TASK FORCE BRIEFING

JUNE 10, 2014

AGENDA

Task Force Remarks

AICM Remarks

HDR/PDP/P1 Presentation

A&I – CONSTRUCTION MANAGEMENT

On-Site Activity

Communication Plan

Construction Manager at Risk

STATE OF WYOMING
Department of Administration & Information
Construction Management

JOINT LEGISLATIVE & EXECUTIVE TASK FORCE BRIEFING

JUNE 10, 2014

AGENDA

Capitol Update – Space Planning
Capitol Update – Building
Herschler Update
Pioneer Site Update
Systems Update
Next Steps

HDR
PDP
PLAN

Capitol Update

- Space Planning

HDR
PDP
PLAN

Capitol Update

- Space Planning

- Cheyenne



OWNED / LEASED ANALYSIS - OFFICE SPACE

Space Planning

- Cheyenne
- Capitol Square



OWNED / LEASED ANALYSIS - OFFICE SPACE

SEA 43

2ND FLOOR – SEA 43



2ND FLOOR – SEA 43



3RD FLOOR – SEA 43



3RD FLOOR – SEA 43



1ST FLOOR – SEA 43



1ST FLOOR – SEA 43



GARDEN LEVEL – SEA 43



GARDEN LEVEL – SEA 43



OPTION A

2ND FLOOR – OPTION A



3RD FLOOR – OPTION A



1ST FLOOR – OPTION A



1ST FLOOR – OPTION A



1ST FLOOR – OPTION A



GARDEN LEVEL – OPTION A



OPTION B

2ND FLOOR – OPTION B



3RD FLOOR – OPTION B



1ST FLOOR – OPTION B



GARDEN LEVEL – OPTION B



OPTION C

2ND FLOOR – OPTION C



3RD FLOOR – OPTION C



1ST FLOOR – OPTION C



GARDEN LEVEL – OPTION C



SEA 43

OPTION A

OPTION B

OPTION C

SEA 43



OPTION A



OPTION B



OPTION C



SEA 43	OPTION A	OPTION B	OPTION C



SEA 43	OPTION A	OPTION B	OPTION C



Capitol Update

- Building

HDR
PDP
PLAN

Two Parallel Tracks

- Needs of the Users
- Needs of the Building

Space Planning



Space Planning



FIRST LEVEL

CAPITOL SPACE PLANNING

140530 - GS

1/16" = 1'-0"

ROBERT SILMAN ASSOCIATES
STRUCTURAL ENGINEERS

PRINCIPALS
Joseph F. Tortorella
Kirk Mettam
Nat Oppenheimer

Edmund P. Meade
Vassil Draganov
Scott Hughes
Alastair C. Elliott
John McCue

Robert Silman
President Emeritus

88 University Place
New York, NY 10003
212.620.7970
www.silman.com

WYOMING STATE CAPITOL
TEST PIT SUMMARY

Test Pit Number:	TP-1	**Date(s) on Site:**	May 13-16
Room:	B67	**RSA Project #:**	15142.01
Phase:	III - 1917	**Documentation:**	AG



OBSERVATIONS
Concrete footing is the size indicated on the drawings.
Concrete footing is not centered on the column.

ROBERT SILMAN ASSOCIATES
STRUCTURAL ENGINEERS

PRINCIPALS
Joseph F. Tortorella
Kirk Mettam
Nat Oppenheimer

Edmund P. Meade
Vassil Draganov
Scott Hughes
Alastair C. Elliott
John McCue

Robert Silman
President Emeritus

88 University Place
New York, NY 10003
212.620.7970
www.silman.com

WYOMING STATE CAPITOL
TEST PIT SUMMARY

Test Pit Number:	TP-2	**Date(s) on Site:**	May 13-16
Room:	B85W	**RSA Project #:**	15142.01
Phase:	I – 1888	**Documentation:**	AG



OBSERVATIONS
Block stone foundation sitting on concrete pad.
Bottom of footing depth varies.
Footing is only 22" deep not 30" deep per the drawings.
Footing projects each side of the wall further than shown on the drawings.
The stone stops at the end of the wall per the drawings.

ROBERT SILMAN ASSOCIATES
STRUCTURAL ENGINEERS

PRINCIPALS
Joseph F. Tortorella
Kirk Mettam
Nat Oppenheimer

Edmund P. Meade
Vassil Draganov
Scott Hughes
Alastair C. Elliott
John McCue

Robert Silman
President Emeritus

88 University Place
New York, NY 10003
212.620.7970
www.silman.com

WYOMING STATE CAPITOL
TEST PIT SUMMARY

Test Pit Number:	TP-7	**Date(s) on Site:**	May 13-16
Room:	B85N	**RSA Project #:**	15142.01
Phase:	I - 1888	**Documentation:**	NRH



OBSERVATIONS
Block stone foundation sitting on concrete pad.
Footing steps out in with in all directions as shown on the drawings.
Footing is deeper than typical 1888 footing.
Footing at rotunda is deeper than the typical but not as deep as shown on the drawings.
Footing projects further than shown on the drawings.

ROBERT SILMAN ASSOCIATES
STRUCTURAL ENGINEERS

PRINCIPALS
Joseph F. Tortorella
Kirk Mettam
Nat Oppenheimer

Edmund P. Meade
Vassil Draganov
Scott Hughes
Alastair C. Elliott
John McCue

Robert Silman
President Emeritus

88 University Place
New York, NY 10003
212.620.7970
www.silman.com

WYOMING STATE CAPITOL
TEST PIT SUMMARY

Test Pit Number:	TP-11	**Date(s) on Site:**	May 13-16
Room:	B31	**RSA Project #:**	15142.01
Phase:	I -1888 & II - 1890	**Documentation:**	AG

OBSERVATIONS
Phase I – 1888 Block stone foundation sitting on concrete pad.
Phase II – 1890 Rubble stone foundation wall sitting on concrete pad.
Both footings are approximately the same depth.
Bottom of footing depth varies.
Bottom of footing is 22" on average below slab not 2'-6 as shown on the drawings.
Floor slab has wire mesh and is modern construction.

ROBERT SILMAN ASSOCIATES
STRUCTURAL ENGINEERS

PRINCIPALS
Joseph F. Tortorella
Kirk Mettam
Nat Oppenheimer

Edmund P. Meade
Vassil Draganov
Scott Hughes
Alastair C. Elliott
John McCue

Robert Silman
President Emeritus

88 University Place
New York, NY 10003
212.620.7970
www.silman.com

WYOMING STATE CAPITOL
TEST PIT SUMMARY

Test Pit Number:	TP-9	**Date(s) on Site:**	May 13-16
Room:	B85N	**RSA Project #:**	15142.01
Phase:	I - 1988	**Documentation:**	AG

OBSERVATIONS
Block and rubble stone foundation sitting on concrete pad.
Footing is wider south of exterior wall as shown on the drawings.
Footing is not as deep as shown on the drawings.

OBSERVATIONS
Footing consists of both large block stones and smaller rubble stones mortared together.
Stones are of differing materials.

OBSERVATIONS
Plaster was removed at cracks in west wall to determine extend to deterioration.
Cracks extend into masonry wall.
Mortar is severely deteriorated.

DRAWINGS



PLAN



SECTION A–A

ROBERT SILMAN ASSOCIATES
STRUCTURAL ENGINEERS

PRINCIPALS
Joseph F. Tortorella
Kirk Mettam
Nat Oppenheimer

Edmund P. Meade
Vassil Draganov
Scott Hughes
Alastair C. Elliott
John McCue

Robert Silman
President Emeritus

88 University Place
New York, NY 10003
212.620.7970
www.silman.com

WYOMING STATE CAPITOL
TEST PIT SUMMARY

Test Pit Number:	TP-12	**Date(s) on Site:**	May 13-16
Room:	B37	**RSA Project #:**	15142.01
Phase:	I -1888	**Documentation:**	AG



OBSERVATIONS
Block stone foundation sitting on concrete pad.
Test pit revealed corroded and failed steam pipe adjacent to existing footing. Work was stopped on test pit until the pipe could be repaired.
Block stone foundation follow the diagonal line of the wall above.

From the Test Pit Findings to Creating a Logical Plan



From the Test Pit Findings to Creating a Logical Plan



From the Test Pit Findings to Creating a Logical Plan



1 CONDITION "A" AT WINDOWS - CONCEPT FOUNDATION
1" = 1'-0"
0 6" 1'-0" 2'-0"



2 CONDITION "B" AT SHALLOW LOWERED SLAB - CONCEPT FOUNDATION
1" = 1'-0"
0 6" 1'-0" 2'-0"

From the Test Pit Findings to Creating a Logical Plan



From the Test Pit Findings to Creating a Logical Plan



1 TRENCH SECTION ACROSS EAST CORRIDOR

1" = 1'-0"

0 6" 1'-0" 2'-0"

From the Test Pit Findings to Creating a Logical Plan



1 TRENCH SECTION ACROSS WEST CORRIDOR - WIDE PORTION

1" = 1'-0"

0 6" 1'-0" 2'-0"

From the Test Pit Findings to Creating a Logical Plan



1 TRENCH SECTION ACROSS WEST CORRIDOR - NARROW PORTION
1" = 1'-0"

From the Test Pit Findings to Creating a Logical Plan



Letting the Building Work to Our Advantage



1 GARDEN LEVEL HVAC PLAN

SCALE: 1/16"=1'-0"

0 8 16 32 FEET

Letting the Building Work to Our Advantage

LEGEND

EQUIPMENT



NOTES

1. TOILET EXHAUST FAN
2. HVAC EQUIPMENT
3. SMOKE EXHAUST MAKE UP AIR VIA DOORS
4. RISER & BASEMENT SUPPLY
5. SMOKE EXHAUST MAKE UP EQUIPMENT
6. RISER TO 1ST FLOOR

1 GARDEN LEVEL HVAC PLAN

SCALE: 1/16"=1'-0"

0 8 16 32 FEET

Letting the Building Work to Our Advantage

LEGEND

EQUIPMENT

EXHAUST DUCT WORK



NOTES

1. TOILET EXHAUST FAN
2. HVAC EQUIPMENT
3. SMOKE EXHAUST MAKE UP AIR VIA DOORS
4. RISER & BASEMENT SUPPLY
5. SMOKE EXHAUST MAKE UP EQUIPMENT
6. RISER TO 1ST FLOOR

1 GARDEN LEVEL HVAC PLAN

SCALE: 1/16"=1'-0"

0 8 16 32 FEET

Letting the Building Work to Our Advantage

LEGEND

- EQUIPMENT
- EXHAUST DUCT WORK
- OUTSIDE AIR DUCT WORK



NOTES

1. TOILET EXHAUST FAN
2. HVAC EQUIPMENT
3. SMOKE EXHAUST MAKE UP AIR VIA DOORS
4. RISER & BASEMENT SUPPLY
5. SMOKE EXHAUST MAKE UP EQUIPMENT
6. RISER TO 1ST FLOOR

1 GARDEN LEVEL HVAC PLAN

SCALE: 1/16"=1'-0"

0 8 16 32 FEET

Letting the Building Work to Our Advantage

LEGEND

- EQUIPMENT
- EXHAUST DUCT WORK
- OUTSIDE AIR DUCT WORK
- BELOW SLAB SUPPLY AIR
- SUPPLY AIR DUCT WORK



1 GARDEN LEVEL HVAC PLAN

SCALE: 1/16"=1'-0"

0 8 16 32 FEET

NOTES

1. TOILET EXHAUST FAN
2. HVAC EQUIPMENT
3. SMOKE EXHAUST MAKE UP AIR VIA DOORS
4. RISER & BASEMENT SUPPLY
5. SMOKE EXHAUST MAKE UP EQUIPMENT
6. RISER TO 1ST FLOOR

Letting the Building Work to Our Advantage

LEGEND

- EQUIPMENT
- EXHAUST DUCT WORK
- OUTSIDE AIR DUCT WORK
- BELOW SLAB SUPPLY AIR
- SUPPLY AIR DUCT WORK
- RETURN AIR DUCT WORK

NOTE: RETURN AIR WILL BE VIA CEILING/SOFFIT BACK TO RETURN AIR SHAFTS TO UNITS.



1 GARDEN LEVEL HVAC PLAN

SCALE: 1/16"=1'-0"

0 8 16 32 FEET

NOTES

1. TOILET EXHAUST FAN
2. HVAC EQUIPMENT
3. SMOKE EXHAUST MAKE UP AIR VIA DOORS
4. RISER & BASEMENT SUPPLY
5. SMOKE EXHAUST MAKE UP EQUIPMENT
6. RISER TO 1ST FLOOR

Letting the Building Work to Our Advantage



NOTES

1. TOILET EXHAUST FAN
2. HVAC EQUIPMENT
3. SMOKE EXHAUST MAKE UP AIR VIA DOORS
4. RISER & BASEMENT SUPPLY
5. SMOKE EXHAUST MAKE UP EQUIPMENT
6. RISER TO 1ST FLOOR

1 GARDEN LEVEL HVAC PLAN

SCALE: 1/16"=1'-0"

0 8 16 32 FEET

Letting the Building Work to Our Advantage



Letting the Building Work to Our Advantage

LEGEND

EQUIPMENT



NOTES

1. TOILET EXHAUST FAN
2. FAN COIL UNIT LOCATED IN GARDEN LEVEL FLOOR SPACE BELOW
3. SUPPLY DUCT WORK UNDER STAIR

1 FIRST FLOOR HVAC PLAN

SCALE: 1/16"=1'-0"

0 8 16 32 FEET

Letting the Building Work to Our Advantage

LEGEND

EQUIPMENT

EXHAUST DUCT WORK



NOTES

1. TOILET EXHAUST FAN
2. FAN COIL UNIT LOCATED IN GARDEN LEVEL FLOOR SPACE BELOW
3. SUPPLY DUCT WORK UNDER STAIR

1 FIRST FLOOR HVAC PLAN

SCALE: 1/16"=1'-0"

0 8 16 32 FEET

Letting the Building Work to Our Advantage

LEGEND

- EQUIPMENT
- EXHAUST DUCT WORK
- OUTSIDE AIR DUCT WORK



NOTES

1. TOILET EXHAUST FAN
2. FAN COIL UNIT LOCATED IN GARDEN LEVEL FLOOR SPACE BELOW
3. SUPPLY DUCT WORK UNDER STAIR

1 FIRST FLOOR HVAC PLAN

SCALE: 1/16"=1'-0"

0 8 16 32 FEET

Letting the Building Work to Our Advantage

LEGEND

- EQUIPMENT
- EXHAUST DUCT WORK
- OUTSIDE AIR DUCT WORK
- SUPPLY AIR DUCT WORK



NOTES

1. TOILET EXHAUST FAN
2. FAN COIL UNIT LOCATED IN GARDEN LEVEL FLOOR SPACE BELOW
3. SUPPLY DUCT WORK UNDER STAIR

1 FIRST FLOOR HVAC PLAN

SCALE: 1/16"=1'-0"

0 8 16 32 FEET

Letting the Building Work to Our Advantage

LEGEND

- EQUIPMENT
- EXHAUST DUCT WORK
- OUTSIDE AIR DUCT WORK
- SUPPLY AIR DUCT WORK
- RETURN AIR DUCT WORK

NOTE: RETURN AIR WILL BE VIA CEILING/SOFFIT BACK TO RETURN AIR SHAFTS TO UNITS.



NOTES

1. TOILET EXHAUST FAN
2. FAN COIL UNIT LOCATED IN GARDEN LEVEL FLOOR SPACE BELOW
3. SUPPLY DUCT WORK UNDER STAIR

1 FIRST FLOOR HVAC PLAN

SCALE: 1/16"=1'-0"

0 8 16 32 FEET

Letting the Building Work to Our Advantage



Letting the Building Work to Our Advantage

LEGEND

EQUIPMENT



NOTES

1. TOILET EXHAUST FAN
2. SUPPLY DUCT DOWN FROM ATTIC

1 SECOND FLOOR HVAC PLAN

SCALE: 1/16"=1'-0"

0 8 16 32 FEET

Letting the Building Work to Our Advantage

LEGEND

EQUIPMENT

EXHAUST DUCT WORK



NOTES

1. TOILET EXHAUST FAN
2. SUPPLY DUCT DOWN FROM ATTIC

1 SECOND FLOOR HVAC PLAN

SCALE: 1/16"=1'-0"

0 8 16 32 FEET

Letting the Building Work to Our Advantage

LEGEND

- EQUIPMENT
- EXHAUST DUCT WORK
- OUTSIDE AIR DUCT WORK



NOTES

1. TOILET EXHAUST FAN
2. SUPPLY DUCT DOWN FROM ATTIC

1 SECOND FLOOR HVAC PLAN

SCALE: 1/16"=1'-0"

0 8 16 32 FEET

Letting the Building Work to Our Advantage

LEGEND

- EQUIPMENT
- EXHAUST DUCT WORK
- OUTSIDE AIR DUCT WORK
- SUPPLY AIR DUCT WORK



NOTES

1. TOILET EXHAUST FAN
2. SUPPLY DUCT DOWN FROM ATTIC

1 SECOND FLOOR HVAC PLAN

SCALE: 1/16"=1'-0"

0 8 16 32 FEET

Letting the Building Work to Our Advantage

LEGEND

- EQUIPMENT
- EXHAUST DUCT WORK
- OUTSIDE AIR DUCT WORK
- SUPPLY AIR DUCT WORK
- RETURN AIR DUCT WORK

NOTE: RETURN AIR WILL BE VIA CEILING/SOFFIT BACK TO RETURN AIR SHAFTS TO UNITS.



NOTES

1. TOILET EXHAUST FAN
2. SUPPLY DUCT DOWN FROM ATTIC

1 SECOND FLOOR HVAC PLAN

SCALE: 1/16"=1'-0"

0 8 16 32 FEET

Letting the Building Work to Our Advantage



Letting the Building Work to Our Advantage

LEGEND

EQUIPMENT



NOTES

1. TOILET EXHAUST FAN
2. SUPPLY GRILLE FED FROM ATTIC ABOVE
3. SUPPLY RISER TO 2ND FLOOR BELOW
4. RETURN RISER

1 THIRD FLOOR HVAC PLAN

SCALE: 1/16"=1'-0"

0 8 16 32 FEET

Letting the Building Work to Our Advantage

LEGEND

EQUIPMENT

EXHAUST DUCT WORK



NOTES

1. TOILET EXHAUST FAN
2. SUPPLY GRILLE FED FROM ATTIC ABOVE
3. SUPPLY RISER TO 2ND FLOOR BELOW
4. RETURN RISER

1 THIRD FLOOR HVAC PLAN

SCALE: 1/16"=1'-0"

0 8 16 32 FEET

Letting the Building Work to Our Advantage

LEGEND

- EQUIPMENT
- EXHAUST DUCT WORK
- OUTSIDE AIR DUCT WORK



NOTES

1. TOILET EXHAUST FAN
2. SUPPLY GRILLE FED FROM ATTIC ABOVE
3. SUPPLY RISER TO 2ND FLOOR BELOW
4. RETURN RISER

1 THIRD FLOOR HVAC PLAN

SCALE: 1/16"=1'-0"

0 8 16 32 FEET

Letting the Building Work to Our Advantage

LEGEND

- EQUIPMENT
- EXHAUST DUCT WORK
- OUTSIDE AIR DUCT WORK
- SUPPLY AIR DUCT WORK



NOTES

1. TOILET EXHAUST FAN
2. SUPPLY GRILLE FED FROM ATTIC ABOVE
3. SUPPLY RISER TO 2ND FLOOR BELOW
4. RETURN RISER

1 THIRD FLOOR HVAC PLAN

SCALE: 1/16"=1'-0"

0 8 16 32 FEET

Letting the Building Work to Our Advantage

LEGEND

- EQUIPMENT
- EXHAUST DUCT WORK
- OUTSIDE AIR DUCT WORK
- SUPPLY AIR DUCT WORK
- RETURN AIR DUCT WORK

NOTE: RETURN AIR WILL BE VIA CEILING/SOFFIT BACK TO RETURN AIR SHAFTS TO UNITS.



NOTES

1. TOILET EXHAUST FAN
2. SUPPLY GRILLE FED FROM ATTIC ABOVE
3. SUPPLY RISER TO 2ND FLOOR BELOW
4. RETURN RISER

1 THIRD FLOOR HVAC PLAN

SCALE: 1/16"=1'-0"

0 8 16 32 FEET

Letting the Building Work to Our Advantage



Letting the Building Work to Our Advantage



2 TYPICAL AHU ISOMETRIC SKETCH
NOT TO SCALE

LEGEND

EQUIPMENT



NOTES

1. SMOKE RELIEF HATCH & EQUIPMENT ACCESS
2. SMOKE EXHAUST FAN
3. OA FROM ROTUNDA ABOVE
4. TOILET EXHAUST FAN

1 ATTIC 1 HVAC PLAN
SCALE: 1/16"=1'-0"
0 8 16 32 FEET

Letting the Building Work to Our Advantage



2 TYPICAL AHU ISOMETRIC SKETCH
NOT TO SCALE

LEGEND

- EQUIPMENT
- EXHAUST DUCT WORK



1 ATTIC 1 HVAC PLAN
SCALE: 1/16"=1'-0"
0 8 16 32 FEET

NOTES

1. SMOKE RELIEF HATCH & EQUIPMENT ACCESS
2. SMOKE EXHAUST FAN
3. OA FROM ROTUNDA ABOVE
4. TOILET EXHAUST FAN

Letting the Building Work to Our Advantage



2 TYPICAL AHU ISOMETRIC SKETCH
NOT TO SCALE

LEGEND

- EQUIPMENT
- EXHAUST DUCT WORK
- OUTSIDE AIR DUCT WORK



1 ATTIC 1 HVAC PLAN
SCALE: 1/16"=1'-0"
0 8 16 32 FEET

NOTES

1. SMOKE RELIEF HATCH & EQUIPMENT ACCESS
2. SMOKE EXHAUST FAN
3. OA FROM ROTUNDA ABOVE
4. TOILET EXHAUST FAN

Letting the Building Work to Our Advantage



2 TYPICAL AHU ISOMETRIC SKETCH
NOT TO SCALE

LEGEND

- EQUIPMENT
- EXHAUST DUCT WORK
- OUTSIDE AIR DUCT WORK
- SUPPLY AIR DUCT WORK



NOTES

1. SMOKE RELIEF HATCH & EQUIPMENT ACCESS
2. SMOKE EXHAUST FAN
3. OA FROM ROTUNDA ABOVE
4. TOILET EXHAUST FAN

1 ATTIC 1 HVAC PLAN
SCALE: 1/16"=1'-0"
0 8 16 32 FEET

Letting the Building Work to Our Advantage



2 TYPICAL AHU ISOMETRIC SKETCH
NOT TO SCALE

LEGEND

- EQUIPMENT
- EXHAUST DUCT WORK
- OUTSIDE AIR DUCT WORK
- SUPPLY AIR DUCT WORK
- RETURN AIR DUCT WORK

NOTE: RETURN AIR WILL BE VIA CEILING/SOFFIT BACK TO RETURN AIR SHAFTS TO UNITS.



1 ATTIC 1 HVAC PLAN
SCALE: 1/16"=1'-0"
0 8 16 32 FEET

NOTES

1. SMOKE RELIEF HATCH & EQUIPMENT ACCESS
2. SMOKE EXHAUST FAN
3. OA FROM ROTUNDA ABOVE
4. TOILET EXHAUST FAN

Letting the Building Work to Our Advantage



1 ROTUNDA - ATTIC 2 HVAC PLAN

SCALE: 1/16"=1'-0"

0 8 16 32 FEET

Letting the Building Work to Our Advantage



Letting the Building Work to Our Advantage

LEGEND

EQUIPMENT

EXHAUST DUCT WORK



NOTES

1. SMOKE EXHAUST RETURNS OVER TOP OF ROTUNDA CORNICE.
2. SMOKE EXHAUST FAN TO SMOKE VENT.

1 ROTUNDA - ATTIC 2 HVAC PLAN

SCALE: 1/16"=1'-0"

0 8 16 32 FEET

Letting the Building Work to Our Advantage



LEGEND

- EQUIPMENT
- EXHAUST DUCT WORK
- OUTSIDE AIR DUCT WORK



NOTES

1. SMOKE EXHAUST RETURNS OVER TOP OF ROTUNDA CORNICE.
2. SMOKE EXHAUST FAN TO SMOKE VENT.

1 ROTUNDA - ATTIC 2 HVAC PLAN

SCALE: 1/16"=1'-0"

0 8 16 32 FEET

Letting the Building Work to Our Advantage



Letting the Building Work to Our Advantage



Letting the Building Work to Our Advantage



Letting the Building Work to Our Advantage



Meanwhile, our team

- Continued on site assessments and investigations
- Reviewed closer the Hitchcock & Hitchcock work
- Revisited the record of the Herschler construction
- Started to build the construction documentation
- Developed design ideas for connecting the Capitol to the “northern territories”

Window Documentation



1 SOUTH ELEVATION - WINDOW NUMBERING SYSTEM

1/16" = 1'-0"

0 4'-0" 8'-0" 12'-0"

Window Documentation



Window Documentation



Window Documentation



Selected Window is a Type "C"

- Based on its geometry, muntin pattern, and original operation.

It receives a prefix number "3"

- Based on its location in the 1917 building campaign.

= WINDOW TYPE IS A "3-C"

Window Documentation



Window Documentation

Window Type “1-P”

Number : SE-829C

Window Documentation



Window Type “1-L”

Number : N-353

Window Documentation

Window Type “1-M”

Number : N-552B

Window Documentation

Window Type “2-F”

Number : N-343

Window Documentation

Window Type “3-C”

Number : S-102

Window Documentation

Window Type “3-D”

Number : S-301

Window Documentation

Window Type “3-D”

Number : S-301

Window Documentation



Selected window is in the 200-series

- Based on its location on the second floor of the building.

It receives a prefix letter "S"

- Based on its location on the South side of the building.

= WINDOW NUMBER IS "S-228"

Window Documentation



1 SOUTH ELEVATION - WINDOW REPLACEMENT CAMPAIGNS

GRAPHIC LEGEND
WINDOW CAMPAIGN DATE

- REPLACED POST 1979
- REPLACED PRE 1977
- MODIFIED PRE 1977
- REPLACED 1999
- REPLACED MID-20TH C.?, 1979?, 1985?

Window Documentation

WINDOW EXPOSURE LOCATIONS

BUILDING CAMPAIGN	WINDOW NUMBER	TYPE	ELEVATION	ADDITIONAL NOTES
GARDEN LEVEL				
3	E-035	3-A	EAST	
1	E-051	1-B	EAST	
2	N-063B	2-A	NORTH	
FIRST FLOOR				
1	N-154	1-A	NORTH	
1	N-161	1-B	NORTH	
SECOND FLOOR				
1	S-215A	1-A	SOUTH	
2	S-225	2-A	SOUTH	
3	N-240A	3-A	NORTH	
3	N-266	3-C	NORTH	
3	W-271	3-A	WEST	
3	W-272	3-C	WEST	
THIRD FLOOR				
3	S-301	3-D	SOUTH	
1	S-309	1-H	SOUTH	
1	S-316	1-J	SOUTH	
3	S-328	3-E	SOUTH	
3	E-330	3-H	EAST	INVESTIGATE JAMB DEPTH
3	E-331	3-H	EAST	INVESTIGATE JAMB DEPTH
2	N-343	2-F	NORTH	
2	N-344	2-D	NORTH	

LETTERING SYSTEM BASED UPON:

- GEOMETRY
- MUNTIN PATTERN
- ORIGINAL OPERATION

FACTORS CONSIDERED IN PROBE SELECTION:

- SOLAR ORIENTATION
- BUILDING CAMPAIGN
- WINDOW TYPE
- MINIMIZE DISRUPTION
- AVOID KEY PERSONNEL AREAS

Window Documentation

Window Documentation

Window Documentation

Window Documentation

Window Documentation

WINDOW SCHEDULE

WINDOW NUMBER	TYPE	M.O.	SASH SIZES [ORIG. SPECS]	DEPTH OF JAMB	ORIG. / REPLACEMENT [DATE]	INTERIOR SASH FINISH	INTERIOR FRAME FINISH	COMMENTS
GARDEN LEVEL								
S-000	3-C	3'-5" x 6'-10"	N/A		REPLACEMENT [POST 1977]	UNPAINTED	UNPAINTED	
S-001	3-A	4'-6" x 6'-10"	(2) 40" x 35"		REPLACEMENT [POST 1977]	UNPAINTED	UNPAINTED	2, 4, 6, 12, 13, 14
S-002A	3-A	3'-4" x 6'-10"	(2) 28" x 35"		REPLACEMENT [POST 1977]	UNPAINTED	UNPAINTED	2, 4, 6, 12, 13, 14
S-002B	3-A	3'-4" x 6'-10"	(2) 28" x 35"		REPLACEMENT [POST 1977]	UNPAINTED	UNPAINTED	2, 4, 6, 12, 13, 14
S-003	3-A	4'-6" x 6'-10"	(2) 40" x 35"		REPLACEMENT [POST 1977]	UNPAINTED	UNPAINTED	2, 4, 6, 12, 13, 14
S-004	2-A	4'-0" x 6'-10"	(2) 40" x 35"		REPLACEMENT [POST 1977]	UNPAINTED	UNPAINTED	2, 4, 6, 12, 13, 14
S-005A	2-A	2'-10" x 6'-10"	(2) 28" x 35"		REPLACEMENT [POST 1977]	UNPAINTED	UNPAINTED	2, 4, 6, 12, 13, 14
S-005B	2-A	2'-10" x 6'-10"	(2) 28" x 35"		REPLACEMENT [POST 1977]	UNPAINTED	UNPAINTED	2, 4, 6, 12, 13, 14
S-006	2-A	4'-0" x 6'-10"	(2) 40" x 35"		REPLACEMENT [POST 1977]	UNPAINTED	UNPAINTED	2, 4, 6, 12, 13, 14
S-007	1-A	4'-0" x 6'-10"	(2) 40" x 35"		REPLACEMENT [POST 1977]	UNPAINTED	UNPAINTED	2, 4, 6, 12, 13, 14
S-008	1-A	4'-0" x 6'-10"	(2) 40" x 35"		REPLACEMENT [POST 1977]	UNPAINTED	UNPAINTED	2, 4, 6, 12, 13, 14
S-009	1-A	4'-0" x 6'-10"	(2) 40" x 35"		REPLACEMENT [POST 1977]	UNPAINTED	UNPAINTED	2, 4, 6, 12, 13, 14
W-011	1-A	3'-9" x 6'-10"	(2) 40" x 35"		REPLACEMENT [POST 1977]	UNPAINTED	UNPAINTED	2, 4, 6, 12, 13, 14
W-012	1-A	3'-9" x 6'-10"	(2) 40" x 35"		REPLACEMENT [POST 1977]	UNPAINTED	UNPAINTED	2, 4, 6, 12, 13, 14
W-013	1-B	+/- 2'-3" x 3'-10"	+/- (2) 18" x 18"		REPLACEMENT [POST 1977]	UNPAINTED	UNPAINTED	
E-017	1-B	+/- 2'-3" x 3'-10"	+/- (2) 18" x 18"		REPLACEMENT [POST 1977]	UNPAINTED	UNPAINTED	
E-018	1-A	3'-9" x 6'-10"	(2) 40" x 35"		REPLACEMENT [POST 1977]	UNPAINTED	UNPAINTED	2, 4, 6, 12, 13, 14
E-019	1-A	3'-9" x 6'-10"	(2) 40" x 35"		REPLACEMENT [POST 1977]	UNPAINTED	UNPAINTED	2, 4, 6, 12, 13, 14
S-021	1-A	4'-0" x 6'-10"	(2) 40" x 35"		REPLACEMENT [POST 1977]	UNPAINTED	PAINTED	2, 4, 6, 14
S-022	1-A	4'-0" x 6'-10"	(2) 40" x 35"		REPLACEMENT [POST 1977]	UNPAINTED	PAINTED	2, 4, 6, 12, 14
S-023	1-A	4'-0" x 6'-10"	(2) 40" x 35"		REPLACEMENT [POST 1977]	UNPAINTED	PAINTED	2, 4, 6, 12, 14
S-024	2-A	4'-0" x 6'-10"	(2) 40" x 35"	17"	REPLACEMENT [POST 1977]	UNPAINTED	UNPAINTED	2, 4, 6, 12, 13, 14
S-025A	2-A	2'-10" x 6'-10"	(2) 28" x 35"	11-1/2"	REPLACEMENT [POST 1977]	UNPAINTED	UNPAINTED	2, 4, 6, 12, 13, 14
S-025B	2-A	2'-10" x 6'-10"	(2) 28" x 35"		REPLACEMENT [POST 1977]	UNPAINTED	UNPAINTED	2, 4, 6, 12, 13, 14
S-026	2-A	4'-0" x 6'-10"	(2) 40" x 35"		REPLACEMENT [POST 1977]	UNPAINTED	UNPAINTED	2, 4, 6, 12, 13, 14
S-027	3-A	4'-6" x 6'-10"	(2) 40" x 35"		REPLACEMENT [POST 1977]	UNPAINTED	UNPAINTED	2, 4, 6, 12, 13, 14
S-028A	3-A	3'-4" x 6'-10"	(2) 28" x 35"		REPLACEMENT [POST 1977]	UNPAINTED	UNPAINTED	2, 4, 6, 12, 13, 14
S-028B	3-A	3'-4" x 6'-10"	(2) 28" x 35"		REPLACEMENT [POST 1977]	UNPAINTED	UNPAINTED	2, 4, 6, 12, 13, 14
S-029	3-A	4'-6" x 6'-10"	(2) 40" x 35"		REPLACEMENT [POST 1977]	UNPAINTED	UNPAINTED	2, 4, 6, 12, 13, 14
E-030	3-A	4'-0" x 6'-10"	(2) 40" x 35"		REPLACEMENT [POST 1977]	UNPAINTED	UNPAINTED	2, 4, 6, 12, 13, 14

= Windows Chosen for Probes

TEXT = Actual Conditions, based on observation

TEXT = Assumed Conditions, based on analysis

NOTES KEY

1) Original sash & exterior frame covered w/ metal cladding (screws evident)
2) Extruded metal sash & frame
3) Modified sash components - with wood muntins & operable metal sash
4) Replacement wood stop(s) - Horizontal (H) and/or Vertical (V)
5) New wood
6) Double-pane replacement windows (Thermopane typical)
7) Bad seals/condensation at sash
8) Mortise joints for previous interior shutters
9) Small and large flanking insulated pipes
10) Replacement metal windows w/single-pane glass & applied ext. muntins (tempered glass typ.)
11) Replacement single-pane wood windows, attached with four screws @ N, S, E & W
12) Replacement wood stool
13) Drywall jambs
14) Dropped acoustic ceiling tile

Window Documentation

E-031	3-A	4'-0" x 6'-10"	(2) 40" x 35"		REPLACEMENT [POST 1977]	UNPAINTED	UNPAINTED	2, 4, 6, 12, 13, 14
E-032	3-A	4'-0" x 6'-10"	(2) 40" x 35"		REPLACEMENT [POST 1977]	UNPAINTED	UNPAINTED	2, 4, 6, 12, 13, 14
E-033	3-A	2'-0" x 6'-10"	(2) 15" x 35"		REPLACEMENT [POST 1977]	UNPAINTED	UNPAINTED	
~~E-034~~								
E-035	3-A	2'-0" x 6'-10"	(2) 15" x 35"		REPLACEMENT [POST 1977]	UNPAINTED	UNPAINTED	2, 4, 6, 12, 13, 14
E-036	3-A	4'-0" x 6'-10"	(2) 40" x 35"		REPLACEMENT [POST 1977]	UNPAINTED	UNPAINTED	2, 4, 6, 12, 13, 14
E-037	3-A	4'-0" x 6'-10"	(2) 40" x 35"		REPLACEMENT [POST 1977]	UNPAINTED	UNPAINTED	2, 4, 6, 12, 13, 14
E-038	3-A	4'-0" x 6'-10"	(2) 40" x 35"		REPLACEMENT [POST 1977]	UNPAINTED	UNPAINTED	2, 4, 6, 12, 13, 14
N-039	3-A	4'-6" x 6'-10"	(2) 40" x 35"		REPLACEMENT [POST 1977]	UNPAINTED	UNPAINTED	2, 4, 6, 12, 13, 14
N-040A	3-A	3'-4" x 6'-10"	(2) 28" x 35"		REPLACEMENT [POST 1977]	UNPAINTED	UNPAINTED	2, 4, 6, 12, 13, 14
N-040B	3-A	3'-4" x 6'-10"	(2) 28" x 35"		REPLACEMENT [POST 1977]	UNPAINTED	UNPAINTED	2, 4, 6, 12, 13, 14
N-041	3-A	4'-6" x 6'-10"	(2) 40" x 35"		REPLACEMENT [POST 1977]	UNPAINTED	UNPAINTED	2, 4, 6, 12, 13, 14
N-042	2-A	4'-0" x 6'-10"	(2) 40" x 35"		REPLACEMENT [POST 1977]	UNPAINTED	UNPAINTED	2, 4, 6, 12, 13, 14
N-043A	2-A	2'-10" x 6'-10"	(2) 28" x 35"		REPLACEMENT [POST 1977]	UNPAINTED	UNPAINTED	2, 4, 6, 12, 13, 14
N-043B	2-A	2'-10" x 6'-10"	(2) 28" x 35"		REPLACEMENT [POST 1977]	UNPAINTED	UNPAINTED	2, 4, 6, 12, 13, 14
N-044	2-A	4'-0" x 6'-10"	(2) 40" x 35"		REPLACEMENT [POST 1977]	UNPAINTED	UNPAINTED	2, 4, 6, 12, 13, 14
N-045	1-A	4'-0" x 6'-10"	(2) 40" x 35"		REPLACEMENT [POST 1977]	UNPAINTED	UNPAINTED	2, 4, 6, 12, 13, 14
N-046	1-A	4'-0" x 6'-10"	(2) 40" x 35"		REPLACEMENT [POST 1977]	UNPAINTED	UNPAINTED	2, 4, 6, 12, 13, 14
N-047	1-A	4'-0" x 6'-10"	(2) 40" x 35"		REPLACEMENT [POST 1977]	UNPAINTED	UNPAINTED	2, 4, 6, 12, 13, 14
E-049	1-A	3'-8" x 6'-10"	(2) 40" x 35"		REPLACEMENT [POST 1977]	UNPAINTED	UNPAINTED	2, 4, 6, 12, 13, 14
E-050	1-A	3'-8" x 6'-10"	(2) 40" x 35"		REPLACEMENT [POST 1977]	UNPAINTED	UNPAINTED	2, 4, 6, 12, 13, 14
E-051	1-B	3'-0" x 4'-9"	(2) 26" x 19"		REPLACEMENT [POST 1977]	UNPAINTED	UNPAINTED	
W-055	1-B	3'-0" x 4'-9"	(2) 26" x 19"		REPLACEMENT [POST 1977]	UNPAINTED	UNPAINTED	
W-056	1-A	3'-8" x 6'-10"	(2) 40" x 35"		REPLACEMENT [POST 1977]	UNPAINTED	UNPAINTED	2, 4, 6, 12, 13, 14
W-057	1-A	3'-8" x 6'-10"	(2) 40" x 35"		REPLACEMENT [POST 1977]	UNPAINTED	UNPAINTED	2, 4, 6, 12, 13, 14
N-059	1-A	4'-0" x 6'-10"	(2) 40" x 35"		REPLACEMENT [POST 1977]	UNPAINTED	UNPAINTED	2, 4, 6, 12, 13, 14
N-060	1-A	4'-0" x 6'-10"	(2) 40" x 35"		REPLACEMENT [POST 1977]	UNPAINTED	UNPAINTED	2, 4, 6, 12, 13, 14
N-061	1-A	4'-0" x 6'-10"	(2) 40" x 35"		REPLACEMENT [POST 1977]	UNPAINTED	UNPAINTED	2, 4, 6, 12, 13, 14
N-062	2-A	4'-0" x 6'-10"	(2) 40" x 35"		REPLACEMENT [POST 1977]	UNPAINTED	UNPAINTED	2, 4, 6, 12, 13, 14
N-063A	2-A	2'-10" x 6'-10"	(2) 28" x 35"		REPLACEMENT [POST 1977]	UNPAINTED	UNPAINTED	2, 4, 6, 12, 13, 14
N-063B	2-A	2'-10" x 6'-10"	(2) 28" x 35"		REPLACEMENT [POST 1977]	UNPAINTED	UNPAINTED	2, 4, 6, 12, 13, 14
N-064	2-A	4'-0" x 6'-10"	(2) 40" x 35"		REPLACEMENT [POST 1977]	UNPAINTED	UNPAINTED	2, 4, 6, 12, 13, 14
N-065	3-A	4'-6" x 6'-10"	(2) 40" x 35"		REPLACEMENT [POST 1977]	UNPAINTED	UNPAINTED	2, 4, 6, 12, 13, 14
N-066A	3-A	3'-4" x 6'-10"	(2) 28" x 35"		REPLACEMENT [POST 1977]	UNPAINTED	UNPAINTED	2, 4, 6, 12, 13, 14
N-066B	3-A	3'-4" x 6'-10"	(2) 28" x 35"		REPLACEMENT [POST 1977]	UNPAINTED	UNPAINTED	2, 4, 6, 12, 13, 14
N-067	3-A	4'-6" x 6'-10"	(2) 40" x 35"		REPLACEMENT [POST 1977]	UNPAINTED	UNPAINTED	2, 4, 6, 12, 13, 14
W-068	3-A	4'-0" x 6'-10"	(2) 40" x 35"		REPLACEMENT [POST 1977]	UNPAINTED	UNPAINTED	2, 4, 6, 12, 13, 14
W-069	3-A	4'-0" x 6'-10"	(2) 40" x 35"		REPLACEMENT [POST 1977]	UNPAINTED	UNPAINTED	2, 4, 6, 12, 13, 14

= Windows Chosen for Probes

TEXT = Actual Conditions, based on observation

TEXT = Assumed Conditions, based on analysis

NOTES KEY

1) Original sash & exterior frame covered w/ metal cladding (screws evident)
2) Extruded metal sash & frame
3) Modified sash components - with wood muntins & operable metal sash
4) Replacement wood stop(s) - Horizontal (H) and/or Vertical (V)
5) New wood
6) Double-pane replacement windows (Thermopane typical)
7) Bad seals/condensation at sash
8) Mortise joints for previous interior shutters
9) Small and large flanking insulated pipes
10) Replacement metal windows w/single-pane glass & applied ext. muntins (tempered glass typ.)
11) Replacement single-pane wood windows, attached with four screws @ N, S, E & W
12) Replacement wood stool
13) Drywall jambs
14) Dropped acoustic ceiling tile

Window Documentation

N-352	1-J	+/- 3'-9" x 3'-6"		12-1/4"	ORIGINAL	UNPAINTED ORIG. WOOD	STAINED	1, 4	
N-353	1-L	+/- 8'-8" x 5'-10"		3-1/2"	ORIGINAL	UNPAINTED ORIG. WOOD	STAINED	1 (Frame Only)	Recessed Panel & Applied Wood Strip @ Arch
N-354	1-J	+/- 3'-9" x 3'-6"		12-1/4"	ORIGINAL	UNPAINTED ORIG. WOOD	STAINED	1, 4	
W-356	1-H	3'-9" x 4'-0"	(1) 40" x 38"	4-1/2"	REPLACEMENT [POST 1977]	UNPAINTED NEWER METAL	NEWER STAINED TRIM	2, 4, 6	New Wood Components
W-357	1-H	3'-9" x 4'-0"	(1) 40" x 38"	4-1/2"	REPLACEMENT [POST 1977]	UNPAINTED NEWER METAL	NEWER STAINED TRIM	2, 4, 6	New Wood Components
N-358	1-H	4'-0" x 4'-0"	(1) 40" x 38"	3-1/2"	REPLACEMENT [1977]	STAINED WOOD & PAINTED METAL	STAINED	2, 4	Interior Floor Higher than Exterior Sill
N-359	1-H	4'-0" x 4'-0"	(1) 40" x 38"	3-1/2"	REPLACEMENT [1977]	STAINED WOOD & PAINTED METAL	STAINED	2, 4	Interior Floor Higher than Exterior Sill
N-360	1-H	4'-0" x 4'-0"	(1) 40" x 38"	3-1/2"	REPLACEMENT [1977]	STAINED WOOD & PAINTED METAL	STAINED	2, 4	Interior Floor Higher than Exterior Sill
N-361	1-H	4'-0" x 4'-0"	(1) 40" x 38"	3-1/2"	REPLACEMENT [1977]	STAINED WOOD & PAINTED METAL	STAINED	2, 4	Interior Floor Higher than Exterior Sill
N-362	2-D	+/- 4'-0" x 3'-6"	40" x 28" OVERALL	5-1/2"	ORIGINAL	STAINED WOOD & PAINTED METAL	STAINED	1, 3, 4	Bolection Molding & Probable Replacement Stool
N-363	2-F	+/- 7'-0" x 4'-3"	76" x 34" OVERALL	5"	ORIGINAL	STAINED WOOD & PAINTED METAL	STAINED	1, 3, 4	Metal Straps, Recessed Panels & Filler Piece @ Jamb
N-365	3-D	+/- 4'-5" x 3'-6"		8-1/2"	ORIGINAL	STAINED WOOD & PAINTED METAL	STAINED	1, 3, 4 (H only)	Trim Cut for Restroom Partition
N-366	3-E	+/- 8'-0" x 4'-3"		9-1/2"	ORIGINAL	STAINED WOOD & PAINTED METAL	STAINED	1, 3, 4 (H only)	Flush panel & Noted +/- 4" Weigh Pocket @ Ea. Side
N-367	3-D	+/- 4'-5" x 3'-6"		9-1/4"	ORIGINAL	STAINED WOOD & PAINTED METAL	STAINED	1, 3, 4 (H only)	Flush panel
W-368	3-H	4'-0" x 4'-0"	(1) 40" x 38"	4-1/2"	REPLACEMENT [1977]	PAINTED METAL	STAINED	2, 4 (H only)	
W-369	3-H	4'-0" x 4'-0"	(1) 40" x 38"	4-1/2"	REPLACEMENT [1977]	PAINTED METAL	STAINED	2, 4	
W-370	3-H	4'-0" x 4'-0"	(1) 40" x 38"	4-1/2"	REPLACEMENT [1977]	PAINTED METAL	STAINED	2, 4 (H only)	
W-374	3-H	4'-0" x 4'-0"	(1) 40" x 38"	7"	REPLACEMENT [1977]	PAINTED METAL	STAINED	2, 4 (H only)	
W-375	3-H	4'-0" x 4'-0"	(1) 40" x 38"	7"	REPLACEMENT [1977]	PAINTED METAL	STAINED	2, 4 (H only)	Lugged Cornice
W-376	3-H	4'-0" x 4'-0"	(1) 40" x 38"	7"	REPLACEMENT [1977]	PAINTED METAL	STAINED	2, 4 (H only)	Lugged Cornice
S-415	1-K	+/- 12'-6" x 6'-4"	(1) 46" x 61" FLANKED BY (2) 36" x 50" (1) EA. SIDE	3-1/2"	ORIGINAL [ASSUMED]	UNPNTD ORIG. WOOD [ASSUMED]	STAINED	1	Cladding assumed from Int. Observation
FLR. TOTAL:	67								
E-533A	1-M	2'-9" x 3'-4"			UNKNOWN			Duct	
E-533B	1-M	2'-9" x 3'-4"			ORIGINAL [MODIFIED]			Roof Access Hatch	
E-535A	1-M	2'-9" x 3'-4"			UNKNOWN			Duct	
E-533B	1-M	2'-9" x 3'-4"			ORIGINAL	PAINTED ASSUMED ORIG. WOOD	PAINTED WOOD	Single-Pane Glass	
N-552A	1-M	2'-9" x 3'-4"			ORIGINAL	PAINTED ASSUMED ORIG. WOOD	PAINTED WOOD	Single-Pane Glass	
N-552B	1-M	2'-9" x 3'-4"			ORIGINAL	PAINTED ASSUMED ORIG. WOOD	PAINTED WOOD	Single-Pane Glass	
N-554A	1-M	2'-9" x 3'-4"			ORIGINAL	PAINTED ASSUMED ORIG. WOOD	PAINTED WOOD	Single-Pane Glass	
N-554B	1-M	2'-9" x 3'-4"			ORIGINAL	PAINTED ASSUMED ORIG. WOOD	PAINTED WOOD	Single-Pane Glass	
W-571A	1-M	2'-9" x 3'-4"			UNKNOWN			Duct (Likely Intake)	
W-571B	1-M	2'-9" x 3'-4"			UNKNOWN			Duct	
W-573A	1-M	2'-9" x 3'-4"			UNKNOWN			Duct	
W-573B	1-M	2'-9" x 3'-4"			UNKNOWN			Duct	
FLR. TOTAL:	12								

= Windows Chosen for Probes

TEXT = Actual Conditions, based on observation

TEXT = Assumed Conditions, based on analysis

NOTES KEY

1) Original sash & exterior frame covered w/ metal cladding (screws evident)
2) Extruded metal sash & frame
3) Modified sash components - with wood muntins & operable metal sash
4) Replacement wood stop(s) - Horizontal (H) and/or Vertical (V)
5) New wood
6) Double-pane replacement windows (Thermopane typical)
7) Bad seals/condensation at sash
8) Mortise joints for previous interior shutters
9) Small and large flanking insulated pipes
10) Replacement metal windows w/single-pane glass & applied ext. muntins (tempered glass typ.)
11) Replacement single-pane wood windows, attached with four screws @ N, S, E & W
12) Replacement wood stool
13) Drywall jambs
14) Dropped acoustic ceiling tile

Window Documentation

SW-601	1-C	4'-8" x 8'-4"			REPLACEMENT [1999]	UNPAINTED METAL	UNPAINTED METAL	10	
S-615	1-C	4'-8" x 8'-4"			REPLACEMENT [1999]	UNPAINTED METAL	UNPAINTED METAL	10	
SE-629	1-C	4'-8" x 8'-4"			REPLACEMENT [1999]	UNPAINTED METAL	UNPAINTED METAL	10	
E-634	1-C	4'-8" x 8'-4"			REPLACEMENT [1999]	UNPAINTED METAL	UNPAINTED METAL	10	Operable - Roof Access Hatch
NE-639	1-C	4'-8" x 8'-4"			REPLACEMENT [1999]	UNPAINTED METAL	UNPAINTED METAL	10	
N-653	1-C	4'-8" x 8'-4"			REPLACEMENT [1999]	UNPAINTED METAL	UNPAINTED METAL	10	
NW-667	1-C	4'-8" x 8'-4"			REPLACEMENT [1999]	UNPAINTED METAL	UNPAINTED METAL	10	
W-672	1-C	4'-8" x 8'-4"			REPLACEMENT [1999]	UNPAINTED METAL	UNPAINTED METAL	10	
SW-701	1-N	4'-11" x 2'-10"			REPLACEMENT [1999]	UNPAINTED METAL	UNPAINTED METAL	10	
S-715	1-N	4'-11" x 2'-10"			REPLACEMENT [1999]	UNPAINTED METAL	UNPAINTED METAL	10	
SE-729	1-N	4'-11" x 2'-10"			REPLACEMENT [1999]	UNPAINTED METAL	UNPAINTED METAL	10	
E-734	1-N	4'-11" x 2'-10"			REPLACEMENT [1999]	UNPAINTED METAL	UNPAINTED METAL	10	
NE-739	1-N	4'-11" x 2'-10"			REPLACEMENT [1999]	UNPAINTED METAL	UNPAINTED METAL	10	
N-753	1-N	4'-11" x 2'-10"			REPLACEMENT [1999]	UNPAINTED METAL	UNPAINTED METAL	10	
NW-767	1-N	4'-11" x 2'-10"			REPLACEMENT [1999]	UNPAINTED METAL	UNPAINTED METAL	10	
W-772	1-N	4'-11" x 2'-10"			REPLACEMENT [1999]	UNPAINTED METAL	UNPAINTED METAL	10	
SW-801A	1-P	1'-9" x 1'-9"			REPLACEMENT [C. 1979]	PAINTED WOOD (NOT ORIG.)	PNTD. WD. (NOT ORIG.)	11	
SW-801B	1-P	1'-9" x 1'-9"			REPLACEMENT [C. 1979]	PAINTED WOOD (NOT ORIG.)	PNTD. WD. (NOT ORIG.)	11	
SW-801C	1-P	1'-9" x 1'-9"			REPLACEMENT [C. 1979]	PAINTED WOOD (NOT ORIG.)	PNTD. WD. (NOT ORIG.)	11	
S-815A	1-P	1'-9" x 1'-9"			REPLACEMENT [C. 1979]	PAINTED WOOD (NOT ORIG.)	PNTD. WD. (NOT ORIG.)	11	
S-815B	1-P	1'-9" x 1'-9"			REPLACEMENT [C. 1979]	PAINTED WOOD (NOT ORIG.)	PNTD. WD. (NOT ORIG.)	11	
S-815C	1-P	1'-9" x 1'-9"			REPLACEMENT [C. 1979]	PAINTED WOOD (NOT ORIG.)	PNTD. WD. (NOT ORIG.)	11	
SE-829A	1-P	1'-9" x 1'-9"			REPLACEMENT [C. 1979]	PAINTED WOOD (NOT ORIG.)	PNTD. WD. (NOT ORIG.)	11	
SE-829B	1-P	1'-9" x 1'-9"			REPLACEMENT [C. 1979]	PAINTED WOOD (NOT ORIG.)	PNTD. WD. (NOT ORIG.)	11	
SE-829C	1-P	1'-9" x 1'-9"			REPLACEMENT [C. 1979]	PAINTED WOOD (NOT ORIG.)	PNTD. WD. (NOT ORIG.)	11	
E-834A	1-P	1'-9" x 1'-9"			REPLACEMENT [C. 1979]	PAINTED WOOD (NOT ORIG.)	PNTD. WD. (NOT ORIG.)	11	Louvered Vent Below
E-834B	1-P	1'-9" x 1'-9"			REPLACEMENT [C. 1979]	PAINTED WOOD (NOT ORIG.)	PNTD. WD. (NOT ORIG.)	11	Louvered Vent Below
E-834C	1-P	1'-9" x 1'-9"			REPLACEMENT [C. 1979]	PAINTED WOOD (NOT ORIG.)	PNTD. WD. (NOT ORIG.)	11	Louvered Vent Below
NE-839A	1-P	1'-9" x 1'-9"			REPLACEMENT [C. 1979]	PAINTED WOOD (NOT ORIG.)	PNTD. WD. (NOT ORIG.)	11	
NE-839B	1-P	1'-9" x 1'-9"			REPLACEMENT [C. 1979]	PAINTED WOOD (NOT ORIG.)	PNTD. WD. (NOT ORIG.)	11	
NE-839C	1-P	1'-9" x 1'-9"			REPLACEMENT [C. 1979]	PAINTED WOOD (NOT ORIG.)	PNTD. WD. (NOT ORIG.)	11	
N-853A	1-P	1'-9" x 1'-9"			REPLACEMENT [C. 1979]	PAINTED WOOD (NOT ORIG.)	PNTD. WD. (NOT ORIG.)	11	
N-853B	1-P	1'-9" x 1'-9"			REPLACEMENT [C. 1979]	PAINTED WOOD (NOT ORIG.)	PNTD. WD. (NOT ORIG.)	11	
N-853C	1-P	1'-9" x 1'-9"			REPLACEMENT [C. 1979]	PAINTED WOOD (NOT ORIG.)	PNTD. WD. (NOT ORIG.)	11	
NW-867A	1-P	1'-9" x 1'-9"			REPLACEMENT [C. 1979]	PAINTED WOOD (NOT ORIG.)	PNTD. WD. (NOT ORIG.)	11	
NW-867B	1-P	1'-9" x 1'-9"			REPLACEMENT [C. 1979]	PAINTED WOOD (NOT ORIG.)	PNTD. WD. (NOT ORIG.)	11	
NW-867C	1-P	1'-9" x 1'-9"			REPLACEMENT [C. 1979]	PAINTED WOOD (NOT ORIG.)	PNTD. WD. (NOT ORIG.)	11	
W-872A	1-P	1'-9" x 1'-9"			REPLACEMENT [C. 1979]	PAINTED WOOD (NOT ORIG.)	PNTD. WD. (NOT ORIG.)	11	Louvered Vent Below
W-872B	1-P	1'-9" x 1'-9"			REPLACEMENT [C. 1979]	PAINTED WOOD (NOT ORIG.)	PNTD. WD. (NOT ORIG.)	11	Louvered Vent Below
W-872C	1-P	1'-9" x 1'-9"			REPLACEMENT [C. 1979]	PAINTED WOOD (NOT ORIG.)	PNTD. WD. (NOT ORIG.)	11	Louvered Vent Below
FLR. TOTAL:	40								

Window Documentation



1 SOUTH ELEVATION - WINDOW EXPOSURE LOCATIONS

1/16" = 1'-0"

0 4'-0" 8'-0" 12'-0"

Window Documentation



1 EAST ELEVATION - WINDOW EXPOSURE LOCATIONS

1/16" = 1'-0"

0 4'-0" 8'-0" 12'-0"

Window Documentation



1 NORTH ELEVATION - WINDOW EXPOSURE LOCATIONS

1/16" = 1'-0"

0 4'-0" 8'-0" 12'-0"

Window Documentation



1 WEST ELEVATION - WINDOW EXPOSURE LOCATIONS

1/16" = 1'-0"

0 4'-0" 8'-0" 12'-0"

Revisiting Hitchcock & Hitchcock



Revisiting Hitchcock & Hitchcock



Revisiting Hitchcock & Hitchcock



Documentation

Documentation

Documentation





1 ROOM 139 NORTH ELEVATION - POINT CLOUD

1/2" = 1'-0"

0 1'-0" 2'-0" 4'-0"



1 ROOM 139 NORTH ELEVATION - ORTHOPHOTOGRAPHY
1/2" = 1'-0"
0 1'-0" 2'-0" 4'-0"

1 ROOM 139 NORTH ELEVATION - ORTHOPHOTOGRAPHY
1/2" = 1'-0"

0 1'-0" 2'-0" 4'-0"

1 ROOM 139 NORTH ELEVATION - ORTHOPHOTOGRAPHY
1/2" = 1'-0"

0 1'-0" 2'-0" 4'-0"

1 ROOM 139 NORTH ELEVATION - ORTHOPHOTOGRAPHY
1/2" = 1'-0"

0 1'-0" 2'-0" 4'-0"

1 ROOM 139 NORTH ELEVATION - AS-FOUND
1/2" = 1'-0"

0 1'-0" 2'-0" 4'-0"

1 ROOM 139 NORTH ELEVATION - AS-FOUND
1/2" = 1'-0"

0 1'-0" 2'-0" 4'-0"


DOWN
UP
UP
UP
DOWN
UP
UP
UP
UP

Looking at the Construction of the Herschler

Looking at the Construction of the Herschler

Looking at the Construction of the Herschler


5'-0"
36'-6"
5'-0"
3'-3"
6'-4"
14'-4"
6'-4"
3'-3"
6" DOWN PIPE
20"x28"
PUBLIC
WATER CLOSETS
3'-3"
14'-3"
1'-6"
8'-6"
1'-6"
14'-3"
3'-3"
WATER CLOSETS FOR OFFICES
TOP 20"x28"
18'-0"
5'-9"
2'-0"
4'
5'-9"
2'-0"
16"x16"
16"x20"
12½"x24"
24"x30½"
8
8
12½"x24"
24"x30½"
8
8
SEE DETAIL
2'-4"x7'-6"x2¼"
G.
Vault.
FURNACE ROOM
Vault.
4'-10"
21'-10"
ENTRANCE HALL
ENTRANCE HALL

WTED-REPLACE-IN-KIND


5'-0"
36'-6"
5'-0"
3'-3"
6'-4"
14'-4"
6'-4"
3'-3"
6" DOWN PIPE
20"x28"
PUBLIC
WATER CLOSETS
3'-3"
14'-3"
1'-6"
8'-6"
1'-6"
14'-3"
3'-3"
WATER CLOSETS FOR OFFICES
TOP 20"x28"
18'-0"
5'-9"
2'-0"
4'
5'-9"
2'-0"
16"x16"
16"x20"
SEE DETAIL
2'-4"x7'-6"x2'-4"
12½"x24"
24"x30½"
8
Vault.
FURNACE ROOM
Vault.
4'-10"
21'-10"
ENTRANCE HALL
ENTRANCE HALL

A New North Connection at the Garden Level



Destructive Examination/ Exposures / Testing & Monitoring

- Window Exposures
- Dimensional Probes
- Structural Probes
- Exposures of Historic Finishes
- Identification of Wood Species
- Materials Testing
- Stone Validation
- Environmental Monitoring
- Structural Monitoring
- Light Fixture Testing

Thank You!

Next Steps

ROBERT SILMAN ASSOCIATES
STRUCTURAL ENGINEERS

PRINCIPALS
Joseph F. Tortorella
Kirk Mettam
Nat Oppenheimer

Edmund P. Meade
Vassil Draganov
Scott Hughes
Alastair C. Elliott
John McCue

Robert Silman
President Emeritus

88 University Place
New York, NY 10003
212.620.7970
www.silman.com

WYOMING STATE CAPITOL
TEST PIT SUMMARY

Test Pit Number:	TP-11	**Date(s) on Site:**	May 13-16
Room:	B31	**RSA Project #:**	15142.01
Phase:	I -1888 & II - 1890	**Documentation:**	AG



OBSERVATIONS
Phase I – 1888 Block stone foundation sitting on concrete pad.
Phase II – 1890 Rubble stone foundation wall sitting on concrete pad.
Both footings are approximately the same depth.
Bottom of footing depth varies.
Bottom of footing is 22" on average below slab not 2'-6 as shown on the drawings.
Floor slab has wire mesh and is modern construction.

OBSERVATIONS
Phase I – 1888 Block stone foundation sitting on concrete pad.
Wood flooring observed adjacent to 1888 block stone.

OBSERVATIONS
Wood boards were observed from test pit looking up. This part of the floor is inconsistent with the typical concrete slab on grade.

DRAWINGS



ELEVATION



SECTION A–A

ROBERT SILMAN ASSOCIATES
STRUCTURAL ENGINEERS

PRINCIPALS
Joseph F. Tortorella
Kirk Mettam
Nat Oppenheimer

Edmund P. Meade
Vassil Draganov
Scott Hughes
Alastair C. Elliott
John McCue

Robert Silman
President Emeritus

88 University Place
New York, NY 10003
212.620.7970
www.silman.com

WYOMING STATE CAPITOL
TEST PIT SUMMARY

Test Pit Number:	TP-2	**Date(s) on Site:**	May 13-16
Room:	B85W	**RSA Project #:**	15142.01
Phase:	I – 1888	**Documentation:**	AG

OBSERVATIONS
Block stone foundation sitting on concrete pad.
Bottom of footing depth varies.
Footing is only 22" deep not 30" deep per the drawings.
Footing projects each side of the wall further than shown on the drawings.
The stone stops at the end of the wall per the drawings.

DRAWINGS



ELEVATION



SECTION A–A

ROBERT SILMAN ASSOCIATES
STRUCTURAL ENGINEERS

PRINCIPALS
Joseph F. Tortorella
Kirk Mettam
Nat Oppenheimer

Edmund P. Meade
Vassil Draganov
Scott Hughes
Alastair C. Elliott
John McCue

Robert Silman
President Emeritus

88 University Place
New York, NY 10003
212.620.7970
www.silman.com

WYOMING STATE CAPITOL
TEST PIT SUMMARY

Test Pit Number:	TP-7	**Date(s) on Site:**	May 13-16
Room:	B85N	**RSA Project #:**	15142.01
Phase:	I - 1888	**Documentation:**	NRH

OBSERVATIONS
Block stone foundation sitting on concrete pad.
Footing steps out in with in all directions as shown on the drawings.
Footing is deeper than typical 1888 footing.
Footing at rotunda is deeper than the typical but not as deep as shown on the drawings.
Footing projects further than shown on the drawings.

OBSERVATIONS
Blocks are cut at various angles and shapes.

OBSERVATIONS
Footing steps up to the typical 22" depth for typical wall.
Footing is deep at Dome support areas as indicated on the drawings.

OBSERVATIONS
Stone sample cut for stone identification.

DRAWINGS



PLAN



SECTION A–A



SECTION B–B



SECTION C–C

ROBERT SILMAN ASSOCIATES
STRUCTURAL ENGINEERS

PRINCIPALS
Joseph F. Tortorella
Kirk Mettam
Nat Oppenheimer

Edmund P. Meade
Vassil Draganov
Scott Hughes
Alastair C. Elliott
John McCue

Robert Silman
President Emeritus

88 University Place
New York, NY 10003
212.620.7970
www.silman.com

WYOMING STATE CAPITOL
TEST PIT SUMMARY

Test Pit Number:	TP-9	**Date(s) on Site:**	May 13-16
Room:	B85N	**RSA Project #:**	15142.01
Phase:	I - 1988	**Documentation:**	AG

OBSERVATIONS
Block and rubble stone foundation sitting on concrete pad.
Footing is wider south of exterior wall as shown on the drawings.
Footing is not as deep as shown on the drawings.

ROBERT SILMAN ASSOCIATES
STRUCTURAL ENGINEERS

PRINCIPALS
Joseph F. Tortorella
Kirk Mettam
Nat Oppenheimer

Edmund P. Meade
Vassil Draganov
Scott Hughes
Alastair C. Elliott
John McCue

Robert Silman
President Emeritus

88 University Place
New York, NY 10003
212.620.7970
www.silman.com

WYOMING STATE CAPITOL
TEST PIT SUMMARY

Test Pit Number:	TP-11	**Date(s) on Site:**	May 13-16
Room:	B31	**RSA Project #:**	15142.01
Phase:	I -1888 & II - 1890	**Documentation:**	AG



OBSERVATIONS
Phase I – 1888 Block stone foundation sitting on concrete pad.
Phase II – 1890 Rubble stone foundation wall sitting on concrete pad.
Both footings are approximately the same depth.
Bottom of footing depth varies.
Bottom of footing is 22" on average below slab not 2'-6 as shown on the drawings.
Floor slab has wire mesh and is modern construction.

OBSERVATIONS
Phase I – 1888 Block stone foundation sitting on concrete pad.
Wood flooring observed adjacent to 1888 block stone.

OBSERVATIONS
Wood boards were observed from test pit looking up. This part of the floor is inconsistent with the typical concrete slab on grade.

DRAWINGS



PLAN



SECTION A–A

ROBERT SILMAN ASSOCIATES
STRUCTURAL ENGINEERS

PRINCIPALS
Joseph F. Tortorella
Kirk Mettam
Nat Oppenheimer

Edmund P. Meade
Vassil Draganov
Scott Hughes
Alastair C. Elliott
John McCue

Robert Silman
President Emeritus

88 University Place
New York, NY 10003
212.620.7970
www.silman.com

WYOMING STATE CAPITOL
TEST PIT SUMMARY

Test Pit Number:	TP-12	**Date(s) on Site:**	May 13-16
Room:	B37	**RSA Project #:**	15142.01
Phase:	I -1888	**Documentation:**	AG

OBSERVATIONS
Block stone foundation sitting on concrete pad.
Test pit revealed corroded and failed steam pipe adjacent to existing footing. Work was stopped on test pit until the pipe could be repaired.
Block stone foundation follow the diagonal line of the wall above.

OBSERVATIONS
Block stone and concrete foundation depth varies.

DRAWINGS



PLAN



SECTION A–A

ROBERT SILMAN ASSOCIATES
STRUCTURAL ENGINEERS

PRINCIPALS
Joseph F. Tortorella
Kirk Mettam
Nat Oppenheimer

Edmund P. Meade
Vassil Draganov
Scott Hughes
Alastair C. Elliott
John McCue

Robert Silman
President Emeritus

88 University Place
New York, NY 10003
212.620.7970
www.silman.com

WYOMING STATE CAPITOL
TEST PIT SUMMARY

Test Pit Number:	TP-13	**Date(s) on Site:**	May 13-16
Room:	B67	**RSA Project #:**	15142.01
Phase:	III -1917	**Documentation:**	AG

OBSERVATIONS
The figure above is looking south under the southern gypsum block partition wall for room B67 to verify if a footing existed under the floor slab. No footing was observed.

OBSERVATIONS
Block stone and concrete foundation depth varies.

DRAWINGS



PLAN



SECTION A–A

ROBERT SILMAN ASSOCIATES
STRUCTURAL ENGINEERS

PRINCIPALS
Joseph F. Tortorella
Kirk Mettam
Nat Oppenheimer

Edmund P. Meade
Vassil Draganov
Scott Hughes
Alastair C. Elliott
John McCue

Robert Silman
President Emeritus

88 University Place
New York, NY 10003
212.620.7970
www.silman.com

WYOMING STATE CAPITOL
TEST PIT SUMMARY

Test Pit Number:	TP-13	**Date(s) on Site:**	May 13-16
Room:	B67	**RSA Project #:**	15142.01
Phase:	III -1917	**Documentation:**	AG

OBSERVATIONS
The figure above is looking south under the southern gypsum block partition wall for room B67 to verify if a footing existed under the floor slab. No footing was observed.

DRAWINGS



PLAN



SECTION A–A



SECTION B–B

DRAWINGS



PLAN



SECTION A–A

ROBERT SILMAN ASSOCIATES
STRUCTURAL ENGINEERS

PRINCIPALS
Joseph F. Tortorella
Kirk Mettam
Nat Oppenheimer

Edmund P. Meade
Vassil Draganov
Scott Hughes
Alastair C. Elliott
John McCue

Robert Silman
President Emeritus

88 University Place
New York, NY 10003
212.620.7970
www.silman.com

WYOMING STATE CAPITOL
TEST PIT SUMMARY

Test Pit Number:	TP-14	**Date(s) on Site:**	May 13-16
Room:	South Exterior	**RSA Project #:**	15142.01
Phase:	I -1888	**Documentation:**	AG

OBSERVATIONS

Footing has been encapsulated with bituthane flashing.
Foam insulation was attached to the outer surface of the flashing.
Counter-flashing was regleted into the stone façade and lapped over the bituthane at grade.
The stepped stone footing surfaces appear to have been filled in with concrete to create a sloped surface for the flashing to adhere to.
The footing configuration shown in the sketch is representative of the design intent. It has not been verified.
If similar to TP 19 on the north facade, the footing consists of two stepped stones and an upper stone that may be roughly coplanar to or part of the stone that is visible above grade.

DRAWINGS



ROBERT SILMAN ASSOCIATES
STRUCTURAL ENGINEERS

PRINCIPALS
Joseph F. Tortorella
Kirk Mettam
Nat Oppenheimer

Edmund P. Meade
Vassil Draganov
Scott Hughes
Alastair C. Elliott
John McCue

Robert Silman
President Emeritus

88 University Place
New York, NY 10003
212.620.7970
www.silman.com

WYOMING STATE CAPITOL
TEST PIT SUMMARY

Test Pit Number:	TP-15	**Date(s) on Site:**	May 13-16
Room:	South Exterior	**RSA Project #:**	15142.01
Phase:	II -1890	**Documentation:**	AG

OBSERVATIONS

Footing has been encapsulated with bituthane flashing.
Foam insulation was attached to the outer surface of the flashing.
Counter-flashing was regleted into the stone façade and lapped over the bituthane at grade.
The stepped stone footing surfaces appear to have been filled in with concrete to create a sloped surface for the flashing to adhere to.
The footing configuration shown in the sketch is representative of the design intent. It has not been verified.

If similar to TP 19 on the north facade, the footing consists of two stepped stones and an upper stone that may be roughly coplanar to or part of the stone that is visible above grade.

DRAWINGS



ROBERT SILMAN ASSOCIATES
STRUCTURAL ENGINEERS

PRINCIPALS
Joseph F. Tortorella
Kirk Mettam
Nat Oppenheimer

Edmund P. Meade
Vassil Draganov
Scott Hughes
Alastair C. Elliott
John McCue

Robert Silman
President Emeritus

88 University Place
New York, NY 10003
212.620.7970
www.silman.com

WYOMING STATE CAPITOL
TEST PIT SUMMARY

Test Pit Number:	TP-16	**Date(s) on Site:**	May 13-16
Room:	East Exterior	**RSA Project #:**	15142.01
Phase:	III -1917	**Documentation:**	AG

OBSERVATIONS
The footing was encapsulated with bituthane flashing.
There were two step outs to the footing.
It was not observed, but Design documents indicate this footing to be entirely made of concrete.

DRAWINGS



ROBERT SILMAN ASSOCIATES
STRUCTURAL ENGINEERS

PRINCIPALS
Joseph F. Tortorella
Kirk Mettam
Nat Oppenheimer

Edmund P. Meade
Vassil Draganov
Scott Hughes
Alastair C. Elliott
John McCue

Robert Silman
President Emeritus

88 University Place
New York, NY 10003
212.620.7970
www.silman.com

WYOMING STATE CAPITOL
TEST PIT SUMMARY

Test Pit Number:	TP-19	**Date(s) on Site:**	May 13-16
Room:	North Exterior	**RSA Project #:**	15142.01
Phase:	II -1890	**Documentation:**	AG

OBSERVATIONS

The footing consists of two stepped stones, the upper stone protruding more than the lower stone.

The topmost stone looked to be part of the rusticated finish stone that ended several inches above the sidewalk slab. This suggests the original grade may have been lower in the past. The lowest measurable point of the concrete fill was measured to be 2" higher than the lowest measured point of concrete fill at TP 11 on the inside of the same wall. This was checked by taking measurements through the window using a 4' level. The 2" discrepancy can be easily attributed to inconsistencies in the concrete pad the footing stones bear on.

Documentation



Window Documentation

Window Type “1-B”

Number : N-148

Window Documentation

Window Type “1-N”

Number : SW-701

Window Type “1-C”

Number : SW-601

Window Documentation

Window Type “1-J”

Number : S-314

Window Documentation

Window Type “2-A”

Number : N-144

Window Documentation

Window Type “2-A”

Number : N-144

Window Documentation

Window Type “3-H”

Number : W-369

Window Documentation

W-074	3-A	4'-0" x 6'-10"	(2) 40" x 35"		REPLACEMENT [POST 1977]	UNPAINTED	UNPAINTED	2, 4, 6, 12, 13, 14	
W-075	3-A	4'-0" x 6'-10"	(2) 40" x 35"		REPLACEMENT [POST 1977]	UNPAINTED	UNPAINTED	2, 4, 6, 12, 13, 14	
W-076	3-A	4'-0" x 6'-10"	(2) 40" x 35"		REPLACEMENT [POST 1977]	UNPAINTED	UNPAINTED	2, 4, 6, 12, 13, 14	
FLR. TOTAL:	70								
FIRST FLOOR									
S-101	3-A	4'-6" x 9'-10"	(2) 40" x 53"	7-1/2"	REPLACEMENT [POST 1977]	UNPAINTED	DARK STAIN	2, 4, 6, 9	
S-102	3-C	8'-0" x 9'-10"		7-1/2"	REPLACEMENT [POST 1977]	UNPAINTED	DARK STAIN	2, 4, 6, 7, 9	
S-103	3-A	4'-6" x 9'-10"	(2) 40" x 53"	7-1/2"	REPLACEMENT [POST 1977]	UNPAINTED	DARK STAIN	2, 4, 6, 9	
S-104	2-A	4'-0" x 9'-10"	(2) 40" x 53"	6-1/2"	REPLACEMENT [POST 1977]	UNPAINTED	DARK STAIN	2, 4, 6, 8	
S-105	2-A	7'-0" x 9'-10"	(2) 76" x 53"	6-1/2"	REPLACEMENT [POST 1977]	UNPAINTED	DARK STAIN	2, 4, 6, 8, 9	
S-106	2-A	4'-0" x 9'-10"	(2) 40" x 53"	6-1/2"	REPLACEMENT [POST 1977]	UNPAINTED	DARK STAIN	2, 4, 6, 8	
S-107	1-B	4'-0" x 9'-6"	(2) 40" x 51"	6"	REPLACEMENT [POST 1977]	UNPAINTED	DARK STAIN	2, 4, 6, 8	
S-108	1-B	4'-0" x 9'-6"	(2) 40" x 51"	6"	REPLACEMENT [POST 1977]	UNPAINTED	DARK STAIN	2, 4, 6, 8	
S-109	1-B	4'-0" x 9'-6"	(2) 40" x 51"	6"	REPLACEMENT [POST 1977]	UNPAINTED	DARK STAIN	2, 4, 6, 8	
S-110	1-B	4'-0" x 9'-6"	(2) 40" x 51"	6"	REPLACEMENT [POST 1977]	UNPAINTED	DARK STAIN	2, 4, 6, 8	
W-111	1-A	3'-8" x 9'-10"	(2) 40" x 53"	16"	REPLACEMENT [POST 1977]	UNPAINTED	DARK STAIN	2, 4, 6, 8	Cut trim @ countertop
W-112	1-A	3'-8" x 9'-10"	(2) 40" x 53"	16"	REPLACEMENT [POST 1977]	UNPAINTED	DARK STAIN	2, 4, 6, 8	Cut trim @ countertop
E-118	1-A	3'-8" x 9'-10"	(2) 40" x 53"	16"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 8, 9 (on L)	Roman Numeral "22"
E-119	1-A	3'-8" x 9'-10"	(2) 40" x 53"	16"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 8, 9 (on R)	
S-120	1-B	4'-0" x 9'-6"	(2) 40" x 51"	6"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 8	
S-121	1-B	4'-0" x 9'-6"	(2) 40" x 51"	6"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 8, 9 (on R)	
S-122	1-B	4'-0" x 9'-6"	(2) 40" x 51"	6"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 8, 7, 9 (on L)	
S-123	1-B	4'-0" x 9'-6"	(2) 40" x 51"	6"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 8, 9 (on R)	
S-124	2-A	4'-0" x 9'-10"	(2) 40" x 53"	6-1/2"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 8, 9	
S-125	2-A	7'-0" x 9'-10"	(2) 76" x 53"	6-1/2"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 8, 9	
S-126	2-A	4'-0 x 9'-10"	(2) 40" x 53"	6-1/2"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 9	
S-127	3-A	4'-6" x 9'-10"	(2) 40" x 53"	7-1/2"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 9	
S-128	3-C	8'-1" x 9'-10"		7-1/2"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 9	
S-129	3-A	4'-7" x 9'-10"	(2) 40" x 53"	7-1/2"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 9	
E-130	3-B	4'-0" x 9'-6"	(2) 40" x 51"	7-1/2"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6	
E-131	3-B	4'-0" x 9'-6"	(2) 40" x 51"	7-1/2"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 7	
E-132	3-B	4'-0" x 9'-6"	(2) 40" x 51"	7-1/2"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 7	
E-133	3-A	2'-1" x 9'-10"		7-1/2"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6	
E-134	3-C	8'-7" x 9'-10"		7-1/2"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 9 (on L)	
E-135	3-A	2'-1" x 9'-10"		7-1/2"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6	
E-136	3-B	4'-0" x 9'-6"	(2) 40" x 51"	7-1/2"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED		
E-137	3-B	4'-0" x 9'-6"	(2) 40" x 51"	7-1/2"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED		
E-138	3-B	4'-0" x 9'-6"	(2) 40" x 51"	7-1/2"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 7	

= Windows Chosen for Probes

TEXT = Actual Conditions, based on observation

TEXT = Assumed Conditions, based on analysis

NOTES KEY

1) Original sash & exterior frame covered w/ metal cladding (screws evident)
2) Extruded metal sash & frame
3) Modified sash components - with wood muntins & operable metal sash
4) Replacement wood stop(s) - Horizontal (H) and/or Vertical (V)
5) Note Removed
6) Double-pane replacement windows (Thermopane typical)
7) Bad seals/condensation at sash
8) Mortise joints for previous interior shutters
9) Small and large flanking insulated pipes
10) Replacement metal windows w/single-pane glass & applied ext. muntins (tempered glass typ.)
11) Replacement single-pane wood windows, attached with four screws @ N, S, E & W
12) Replacement wood stool
13) Drywall jambs
14) Dropped acoustic ceiling tile

N-139	3-A	4'-6" x 9'-10"	(2) 40" x 53"	7-1/2"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 7	
N-140	3-C	8'-0" x 9'-10"		7-1/2"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 9	
N-141	3-A	4'-6" x 9'-10"	(2) 40" x 53"	7-1/2"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 9	
N-142	3-A	4'-1" x 9'-10"	(2) 40" x 53"	6"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 8, 9	Wire Glass all Panes
N-143	2-A	7'-0" x 9'-10"	(2) 76" x 53"	6"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 8	
N-144	2-A	4'-1" x 9'-10"	(2) 40" x 53"	6"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 8	
N-145	1-B	4'-0" x 9'-6"	(2) 40" x 51"	6"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 8	Roman Numeral "9"
N-146	1-B	4'-0" x 9'-6"	(2) 40" x 51"	6"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 7, 8	Roman Numeral "10"
N-147	1-B	4'-0" x 9'-6"	(2) 40" x 51"	6"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 7, 8	
N-148	1-B	4'-0" x 9'-6"	(2) 40" x 51"	6"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 8	
E-149	1-A	3'-8" x 9'-10"	(2) 40" x 53"	16"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 8	Roman Numeral "20"
E-150	1-A	3'-8" x 9'-10"	(2) 40" x 53"	16"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 8	Roman Numeral "19"
N-152	1-A	2'-0" x 9'-10"		16"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 8	Roman Numeral "2"
N-154	1-A	2'-0" x 9'-10"		16"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 7, 8	Dutchmen
W-156	1-A	3'-8" x 9'-10"	(2) 40" x 53"	16"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 8, 9 (on L)	Dutchmen
W-157	1-A	3'-8" x 9'-10"	(2) 40" x 53"	16"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 7, 8, 9 (on R)	Dutchmen
N-158	1-B	4'-0" x 9'-6"	(2) 40" x 51"	6"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 7, 8	Roman Numeral "13," & Dutchmen
N-159	1-B	4'-0" x 9'-6"	(2) 40" x 51"	6"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 8	Roman Numeral "14," & Dutchmen
N-160	1-B	4'-0" x 9'-6"	(2) 40" x 51"	6"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 8	Roman Numeral "15," & Dutchmen
N-161	1-B	4'-0" x 9'-6"	(2) 40" x 51"	6"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 8	Roman Numeral "16," & Dutchmen
N-162	2-A	4'-0" x 9'-10"	(2) 40" x 53"	6-1/2"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 8	Dutchmen
N-163	2-A	7'-0" x 9'-10"	(2) 76" x 53"	6-1/2"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 8	Dutchmen
N-164	2-A	4'-0" x 9'-10"	(2) 40" x 53"	6-1/2"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 8	Wire Glass all Panes & Dutchmen
N-165	3-A	4'-6" x 9'-10"	(2) 40" x 53"	7-1/2"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6	
N-166	3-C	8'-0" x 9'-10"		7-1/2"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 7	
N-167	3-A	4'-6" x 9'-10"	(2) 40" x 53"	7-1/2"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6	
W-168	3-B	4'-0" x 9'-6"	(2) 40" x 51"	7-1/2"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6	
W-169	3-B	4'-0" x 9'-6"	(2) 40" x 51"	7-1/2"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6	
W-170	3-B	4'-0" x 9'-6"	(2) 40" x 51"	7-1/2"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6	
W-174	3-B	4'-0" x 9'-6"	(2) 40" x 51"	7-1/2"	REPLACEMENT [POST 1977]	UNPAINTED	DARK STAIN	2, 4, 6, 9	
W-175	3-B	4'-0" x 9'-6"	(2) 40" x 51"	7-1/2"	REPLACEMENT [POST 1977]	UNPAINTED	DARK STAIN	2, 4, 6	
W-176	3-B	4'-0" x 9'-6"	(2) 40" x 51"	7-1/2"	REPLACEMENT [POST 1977]	UNPAINTED	DARK STAIN	2, 4, 6	
FLR. TOTAL:	65								
SECOND FLOOR									
S-201	3-A	4'-6" x 11'-6"	(2) 40" x 63"	7-1/2"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 7, 9	Cut trim @ dropped ceiling
S-202	3-C	8'-0" x 11'-6"		7-1/2"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 9	Cut trim @ dropped ceiling
S-203	3-A	4'-6" x 11'-6"	(2) 40" x 63"	7"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 9	

= Windows Chosen for Probes

TEXT = Actual Conditions, based on observation

TEXT = Assumed Conditions, based on analysis

NOTES KEY

1) Original sash & exterior frame covered w/ metal cladding (screws evident)
2) Extruded metal sash & frame
3) Modified sash components - with wood muntins & operable metal sash
4) Replacement wood stop(s) - Horizontal (H) and/or Vertical (V)
5) New wood
6) Double-pane replacement windows (Thermopane typical)
7) Bad seals/condensation at sash
8) Mortise joints for previous interior shutters
9) Small and large flanking insulated pipes
10) Replacement metal windows w/single-pane glass & applied ext. muntins (tempered glass typ.)
11) Replacement single-pane wood windows, attached with four screws @ N, S, E & W
12) Replacement wood stool
13) Drywall jambs
14) Dropped acoustic ceiling tile

Window Documentation

S-204	2-A	4'-0" x 11'-6"	(2) 40" x 63"	7"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6	Dropped ceiling @ Stair Landing
S-205	2-A	7'-0" x 11'-6"	(2) 76" x 63"	7"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 7, 9	
S-206	2-A	4'-0" x 11'-6"	(2) 40" x 63"	7"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 7, 9 (on R)	
S-207	1-A	4'-0" x 11'-6"	(2) 40" x 63"	6-1/2"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 7, 8	Roman Numeral "8," & Dutchmen
S-208	1-A	4'-0" x 11'-6"	(2) 40" x 63"	6-1/2"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 8	Roman Numeral "7," & Dutchmen
S-209	1-A	4'-0" x 11'-6"	(2) 40" x 63"	6-1/2"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 8	Roman Numeral "4," & Dutchmen
S-210	1-A	4'-0" x 11'-6"	(2) 40" x 63"	6-1/2"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 8	Roman Numeral "5," & Dutchmen
W-211	1-A	3'-9" x 11'-6"	(2) 40" x 63"	6"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6	
W-212	1-A	3'-9" x 11'-6"	(2) 40" x 63"	6"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6	
S-214	1-A	+/- 2'-5" x 11'-6"	(2) 20" x 63"	4-1/2"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6	
S-215A	1-A	+/- 5'-2" x 11'-6"	(2) 54" x 63"	4-1/2"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 7	
S-215B	1-A	+/- 5'-2" x 11'-6"	(2) 54" x 63"	4-1/2"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 7	
S-216	1-A	+/- 2'-5" x 11'-6"	(2) 20" x 63"	4-1/2"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 7	
E-218	1-A	3'-9" x 11'-6"	(2) 40" x 63"	6"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6	
E-219	1-A	3'-9" x 11'-6"	(2) 40" x 63"	6"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6	
S-220	1-A	4'-0" x 11'-6"	(2) 40" x 63"	6-1/2"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 7, 8	
S-221	1-A	4'-0" x 11'-6"	(2) 40" x 63"	6-1/2"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 8	
S-222	1-A	4'-0" x 11'-6"	(2) 40" x 63"	6-1/2"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 8	
S-223	1-A	4'-0" x 11'-6"	(2) 40" x 63"	6-1/2"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 8	
S-224	2-A	4'-0" x 11'-6"	(2) 40" x 63"	6-1/2"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 8	
S-225	2-A	7'-0" x 11'-6"	(2) 76" x 63"	7"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 7	
S-226	2-A	4'-0" x 11'-6"	(2) 40" x 63"	7-1/4"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 7	
S-227	3-A	4'-6" x 11'-6"	(2) 40" x 63"	6-1/4"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 7, 9	
S-228	3-C	8'-0" x 11'-6"		8"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 7	
S-229	3-A	4'-6" x 11'-6"	(2) 40" x 63"	7-1/4"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 7, 9	
E-230	3-A	4'-0" x 11'-6"	(2) 40" x 63"	7"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 7	
E-231	3-A	4'-0" x 11'-6"	(2) 40" x 63"	7"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 7	
E-232	3-A	4'-0" x 11'-6"	(2) 40" x 63"	7"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6	
E-236	3-A	4'-0" x 11'-6"	(2) 40" x 63"	7"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6	
E-237	3-A	4'-0" x 11'-6"	(2) 40" x 63"	7"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 9	
E-238	3-A	4'-0" x 11'-6"	(2) 40" x 63"	7"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 7	
N-239	3-A	4'-6" x 11'-6"	(2) 40" x 63"	7"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 9	
N-240A	3-A	8'-0" x 11'-6"		8"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 9 (on R)	
N-240B	3-A	INCLUDED IN 240A		8"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 9 (on L)	
N-241	3-A	4'-6" x 11'-6"	(2) 40" x 63"	7"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6	
N-243	2-A	7'-0" x 11'-6"	(2) 76" x 63"	7"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 7	
N-244	2-A	4'-0" x 11'-6"	(2) 40" x 63"	7"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 8	
N-245	1-A	4'-0" x 11'-6"	(2) 40" x 63"	6-1/2"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 8	

= Windows Chosen for Probes

TEXT = Actual Conditions, based on observation

TEXT = Assumed Conditions, based on analysis

NOTES KEY

1) Original sash & exterior frame covered w/ metal cladding (screws evident)
2) Extruded metal sash & frame
3) Modified sash components - with wood muntins & operable metal sash
4) Replacement wood stop(s) - Horizontal (H) and/or Vertical (V)
5) New wood
6) Double-pane replacement windows (Thermopane typical)
7) Bad seals/condensation at sash
8) Mortise joints for previous interior shutters
9) Small and large flanking insulated pipes
10) Replacement metal windows w/single-pane glass & applied ext. muntins (tempered glass typ.)
11) Replacement single-pane wood windows, attached with four screws @ N, S, E & W
12) Replacement wood stool
13) Drywall jambs
14) Dropped acoustic ceiling tile

Window Documentation

N-246	1-A	4'-0" x 11'-6"	(2) 40" x 63"	6-1/2"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 8	
N-247	1-A	4'-0" x 11'-6"	(2) 40" x 63"	6-1/2"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 8	
N-248	1-A	4'-0" x 11'-6"	(2) 40" x 63"	6-1/2"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 8	
E-249	1-A	3'-9" x 11'-6"	(2) 40" x 63"	6"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 9 (on R)	
E-250	1-A	3'-9" x 11'-6"	(2) 40" x 63"	6"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 9 (on L)	
N-252	1-A	+/- 4'-6" x 9'-6"		16"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 9 (on R)	
N-253	1-A	+/- 10'-3" x 9'-6"		5-1/2"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6	
N-254	1-A	+/- 4'-6" x 9'-6"		16"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6	
W-256	1-A	3'-9" x 11'-6"	(2) 40" x 63"	6"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 9 (on R)	
W-257	1-A	3'-9" x 11'-6"	(2) 40" x 63"	6"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 9 (on L)	
N-258	1-A	4'-0" x 11'-6"	(2) 40" x 63"	6-1/2"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 8	Dutchmen
N-259	1-A	4'-0" x 11'-6"	(2) 40" x 63"	6-1/2"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 8	Dutchmen
N-260	1-A	4'-0" x 11'-6"	(2) 40" x 63"	6-1/2"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 8	Dutchmen
N-261	1-A	4'-0" x 11'-6"	(2) 40" x 63"	6-1/2"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 8	Dutchmen
N-262	2-A	4'-0" x 11'-6"	(2) 40" x 63"	6-1/2"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 7	
N-263	2-A	7'-0" x 11'-6"	(2) 76" x 63"	6-1/2"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 7, 9	
N-265	3-A	4'-6" x 11'-6"	(2) 40" x 63"	7-1/2"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 7	Earlier Dutchmen from previous partition
N-266	3-C	8'-0" x 11'-6"		7-1/2"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6	
N-267	3-A	4'-6" x 11'-6"	(2) 40" x 63"	8-1/2"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6	
W-268	3-A	4'-0" x 11'-6"	(2) 40" x 63"	6"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 7	
W-269	3-A	4'-0" x 11'-6"	(2) 40" x 63"	6"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6	
W-270	3-A	4'-0" x 11'-6"	(2) 40" x 63"	6"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 7	
W-271	3-A	4'-6" x 11'-6"		7-1/2"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6	
W-272	3-C	8'-0" x 11'-6"		7-1/2"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6	
W-273	3-A	4'-6" x 11'-6"		6"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 7	
W-274	3-A	4'-0" x 11'-6"	(2) 40" x 63"	6"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 7, 9	
W-275	3-A	4'-0" x 11'-6"	(2) 40" x 63"	6"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6	
W-276	3-A	4'-0" x 11'-6"	(2) 40" x 63"	6"	REPLACEMENT [POST 1977]	UNPAINTED	STAINED	2, 4, 6, 7	
FLR. TOTAL:	69								
S-301	3-D	+/- 4'-5" x 3'-6"		9-1/4"	ORIGINAL	STAINED WOOD & PAINTED METAL	STAINED	1, 3, 4 (H only)	Raised Panel
S-302	3-E	+/- 8'-0" x 4'-3"		9-1/4"	ORIGINAL	STAINED WOOD & PAINTED METAL	STAINED	1, 3, 4 (H only)	Flush panel
S-303	3-D	+/- 4'-5" x 3'-6"		9-1/4"	ORIGINAL	STAINED WOOD & PAINTED METAL	STAINED	1, 3, 4 (H only)	Flush panel
S-304	2-D	+/- 4'-0" x 3'-6"	40" x 28" OVERALL	5-1/2"	ORIGINAL	STAINED WOOD & PAINTED METAL	STAINED	1	Unmodified, with Raised Panel
S-305	2-F	+/- 7'-0" x 4'-3"	76" x 34" OVERALL	5-1/2"	ORIGINAL	STAINED WOOD & PAINTED METAL	STAINED	1, 3, 4	Metal Straps, Filler Piece @ Jamb & Extruded Ext. Sill
S-306	2-D	+/- 4'-0" x 3'-6"	40" x 28" OVERALL	5-1/2"	ORIGINAL	STAINED WOOD & PAINTED METAL	STAINED	1, 3, 4	
S-307	1-H	4'-0" x 4'-0"	(1) 40" x 38"	4"	REPLACEMENT [1977]	PAINTED METAL	STAINED	2, 4	Interior Floor Higher than Exterior Sill
S-308	1-H	4'-0" x 4'-0"	(1) 40" x 38"	4"	REPLACEMENT [1977]	PAINTED METAL	STAINED	2, 4	Interior Floor Higher than Exterior Sill

= Windows Chosen for Probes

TEXT = Actual Conditions, based on observation

TEXT = Assumed Conditions, based on analysis

NOTES KEY

1) Original sash & exterior frame covered w/ metal cladding (screws evident)
2) Extruded metal sash & frame
3) Modified sash components - with wood muntins & operable metal sash
4) Replacement wood stop(s) - Horizontal (H) and/or Vertical (V)
5) New wood
6) Double-pane replacement windows (Thermopane typical)
7) Bad seals/condensation at sash
8) Mortise joints for previous interior shutters
9) Small and large flanking insulated pipes
10) Replacement metal windows w/single-pane glass & applied ext. muntins (tempered glass typ.)
11) Replacement single-pane wood windows, attached with four screws @ N, S, E & W
12) Replacement wood stool
13) Drywall jambs
14) Dropped acoustic ceiling tile

S-309	1-H	4'-0" x 4'-0"	(1) 40" x 38"	4"	REPLACEMENT [1977]	PAINTED METAL	STAINED	2, 4	Interior Floor Higher than Exterior Sill
S-310	1-H	4'-0" x 4'-0"	(1) 40" x 38"	4"	REPLACEMENT [1977]	PAINTED METAL	STAINED	2, 4	Interior Floor Higher than Exterior Sill
W-311	1-H	3'-8" x 4'-0"	(1) 40" x 38"	3-1/2"	REPLACEMENT [1977]	PAINTED METAL	STAINED	2, 4	Interior Floor Higher than Exterior Sill
W-312	1-H	3'-8" x 4'-0"	(1) 40" x 38"	3-1/2"	REPLACEMENT [1977]	PAINTED METAL	STAINED	2, 4	Interior Floor Higher than Exterior Sill
S-314	1-J	2'-8" x 2'-8"		5-1/2"	ORIGINAL	UNPAINTED ORIG. WOOD	STAINED	1, 4	No Interior Screws @ Stops (as are evident @ S-316)
S-315A	1-A	+/- 5'-0 x 5'-4"	(1) 51" x 55"	3-1/2"	REPLACEMENT [1977]	PAINTED METAL	STAINED	2, 4	Interior Floor Higher than Exterior Sill
S-315B	1-A	+/- 5'-0 x 5'-4"	(1) 51" x 55"	3-1/2"	REPLACEMENT [1977]	PAINTED METAL	STAINED	2, 4	Interior Floor Higher than Exterior Sill
S-316	1-J	2'-8" x 2'-8"		5-1/2"	ORIGINAL	UNPAINTED ORIG. WOOD	STAINED	1, 4	Screws Evident @ Stop Replacements
E-318	1-H	3'-8" x 4'-0"	(1) 40" x 38"	3-1/2"	REPLACEMENT [1977]	PAINTED METAL	STAINED	2, 4	Interior Floor Higher than Exterior Sill
E-319	1-H	3'-8" x 4'-0"	(1) 40" x 38"	3-1/2"	REPLACEMENT [1977]	PAINTED METAL	STAINED	2, 4	Interior Floor Higher than Exterior Sill
S-320	1-H	4'-0" x 4'-0"	(1) 40" x 38"	3-1/2"	REPLACEMENT [1977]	PAINTED METAL	STAINED	2, 4	Interior Floor Higher than Exterior Sill
S-321	1-H	4'-0" x 4'-0"	(1) 40" x 38"	4"	REPLACEMENT [1977]	PAINTED METAL	STAINED	2, 4	Interior Floor Higher than Exterior Sill
S-322	1-H	4'-0" x 4'-0"	(1) 40" x 38"	4"	REPLACEMENT [1977]	PAINTED METAL	STAINED	2, 4	Interior Floor Higher than Exterior Sill
S-323	1-H	4'-0" x 4'-0"	(1) 40" x 38"	4"	REPLACEMENT [1977]	PAINTED METAL	STAINED	2, 4	Interior Floor Higher than Exterior Sill
S-324	2-D	+/- 4'-0" x 3'-6"	40" x 28" OVERALL	5-1/2"	ORIGINAL	STAINED WOOD & PAINTED METAL	STAINED	1, 3	Cracked Trim @ Head
S-325	2-F	+/- 7'-0" x 4'-3"	76" x 34" OVERALL	5-1/2"	ORIGINAL	STAINED WOOD & PAINTED METAL	STAINED	1, 3	
S-326	2-D	+/- 4'-0" x 3'-6"	40" x 28" OVERALL	5-1/2"	ORIGINAL	UNPAINTED ORIG. WOOD	STAINED	1 (Frame Only)	Unmodified, with Raised Panel
S-327	3-D	+/- 4'-5" x 3'-6"		7"	ORIGINAL	STAINED WOOD & PAINTED METAL	STAINED	1, 3, 4 (H only)	Flush panel
S-328	3-E	+/- 8'-0" x 4'-3"		7"	ORIGINAL	STAINED WOOD & PAINTED METAL	STAINED	1, 3, 4 (H only)	Flush panel
S-329	3-D	+/- 4'-5" x 3'-6"		7-1/2"	ORIGINAL	STAINED WOOD & PAINTED METAL	STAINED	1, 3, 4 (H only)	Flush panel
E-330	3-H	4'-0" x 4'-0"	(1) 40" x 38"	7"	REPLACEMENT [1977]	PAINTED METAL	STAINED	2, 4 (H only)	
E-331	3-H	4'-0" x 4'-0"	(1) 40" x 38"	4-1/2"	REPLACEMENT [1977]	PAINTED METAL	STAINED	2, 4	
E-332	3-H	4'-0" x 4'-0"	(1) 40" x 38"	4-1/2"	REPLACEMENT [1977]	PAINTED METAL	STAINED	2, 4 (H only)	
E-336	3-H	4'-0" x 4'-0"	(1) 40" x 38"	4-1/4"	REPLACEMENT [1977]	PAINTED METAL	STAINED	2, 4	
E-337	3-H	4'-0" x 4'-0"	(1) 40" x 38"	5"	REPLACEMENT [1977]	PAINTED METAL	STAINED	2, 4	
E-338	3-H	4'-0" x 4'-0"	(1) 40" x 38"	7"	REPLACEMENT [1977]	PAINTED METAL	STAINED	2, 4 (H only)	
N-339	3-D	+/- 4'-5" x 3'-6"		7"	ORIGINAL	STAINED WOOD & PAINTED METAL	STAINED	1, 3, 4 (H only)	Flush panel & Probably Replaced Stool
N-340A	3-G	+/- 8'-0" x 4'-3"		9"	ORIGINAL	STAINED WOOD & PAINTED METAL	STAINED	1, 3, 4 (H only)	Flush panel
N-340B	3-G	INCLUDED IN 340A		9"	ORIGINAL	STAINED WOOD & PAINTED METAL	STAINED	1, 3, 4 (H only)	Flush panel
N-341	3-D	+/- 4'-5" x 3'-6"		7"	ORIGINAL	STAINED WOOD & PAINTED METAL	STAINED	1, 3	Trim Cut for Restroom Partition
N-343	2-F	+/- 7'-0" x 4'-3"	76" x 34" OVERALL	5-1/2"	ORIGINAL	STAINED WOOD & PAINTED METAL	STAINED	1, 3	Metal Straps, Recessed Panels & Filler Piece @ Jamb
N-344	2-D	+/- 4'-0" x 3'-6"	40" x 28" OVERALL	5-1/2"	ORIGINAL	STAINED WOOD & PAINTED METAL	STAINED	1, 3, 4 (H only)	Bolection Molding & Probable Replacement Stool
N-345	1-H	4'-0" x 4'-0"	(1) 40" x 38"	3-1/2"	REPLACEMENT [1977]	PAINTED METAL	STAINED	2, 4	Interior Floor Higher than Exterior Sill
N-346	1-H	4'-0" x 4'-0"	(1) 40" x 38"	3-1/2"	REPLACEMENT [1977]	PAINTED METAL	STAINED	2, 4	Interior Floor Higher than Exterior Sill
N-347	1-H	4'-0" x 4'-0"	(1) 40" x 38"	3-1/2"	REPLACEMENT [1977]	PAINTED METAL	STAINED	2, 4	Interior Floor Higher than Exterior Sill
N-348	1-H	4'-0" x 4'-0"	(1) 40" x 38"	3-1/2"	REPLACEMENT [1977]	PAINTED METAL	STAINED	2, 4	Interior Floor Higher than Exterior Sill
E-349	1-H	3'-9" x 4'-0"	(1) 40" x 38"	4-1/2"	REPLACEMENT [POST 1977]	UNPAINTED NEWER METAL	NEWER STAINED TRIM	2, 4, 6	Interior Floor Higher than Exterior Sill
E-350	1-H	3'-9" x 4'-0"	(1) 40" x 38"	4-1/2"	REPLACEMENT [POST 1977]	UNPAINTED NEWER METAL	NEWER STAINED TRIM	2, 4, 6	

= Windows Chosen for Probes

TEXT = Actual Conditions, based on observation

TEXT = Assumed Conditions, based on analysis

NOTES KEY

1) Original sash & exterior frame covered w/ metal cladding (screws evident)
2) Extruded metal sash & frame
3) Modified sash components - with wood muntins & operable metal sash
4) Replacement wood stop(s) - Horizontal (H) and/or Vertical (V)
5) New wood
6) Double-pane replacement windows (Thermopane typical)
7) Bad seals/condensation at sash
8) Mortise joints for previous interior shutters
9) Small and large flanking insulated pipes
10) Replacement metal windows w/single-pane glass & applied ext. muntins (tempered glass typ.)
11) Replacement single-pane wood windows, attached with four screws @ N, S, E & W
12) Replacement wood stool
13) Drywall jambs
14) Dropped acoustic ceiling tile

Window Documentation

TOTALS:	
BASEMENT:	70
FIRST:	65
SECOND:	69
THIRD:	67
ATTIC:	12
DOME:	40
GROSS TOTAL:	323

= Windows Chosen for Probes

TEXT = Actual Conditions, based on observation

TEXT = Assumed Conditions, based on analysis

NOTES KEY

1) Original sash & exterior frame covered with metal cladding (screws evident)
2) Extruded metal sash & frame
3) Modified sash components - with wood muntins & operable metal sash
4) Replacement wood stop(s) - Horizontal (H) and/or Vertical (V)
5) New wood
6) Double-pane replacement windows (Thermopane typical)
7) Bad seals/condensation at sash
8) Mortise joints for previous interior shutters
9) Small and large flanking insulated pipes
10) Replacement metal windows w/single-pane glass & applied ext. muntins (tempered glass typ.)
11) Replacement single-pane wood windows, attached with four screws @ N, S, E & W
12) Replacement wood stool
13) Drywall jambs
14) Dropped acoustic ceiling tile

Herschler Update

- Data Center
- Exterior Wall Report
- CUP / Connector
- North Drive
- Planning & Design – good bones

GARDEN LEVEL



GARDEN LEVEL



GARDEN LEVEL



Capitol Square
Level III Design & Construction

GARDEN LEVEL



Capitol Square
Level III Design & Construction

GARDEN LEVEL



Capitol Square
Level III Design & Construction

GARDEN LEVEL



GARDEN LEVEL



Capitol Square
Level III Design & Construction

GARDEN LEVEL



GARDEN LEVEL



GARDEN LEVEL



GARDEN LEVEL



GARDEN LEVEL



GARDEN LEVEL



Capitol Square
Level III Design & Construction

GARDEN LEVEL



Capitol Square
Level III Design & Construction

1st Floor





Capitol Square
Level III Design & Construction

1st Floor





Capitol Square
Level III Design & Construction

1st Floor





Capitol Square
Level III Design & Construction

1st Floor



Capitol Square
Level III Design & Construction

1st Floor



Capitol Square

Level III Design & Construction

1st Floor



LOWER LEVEL


+5'
VENDING SEATING
+5'
VENDING SEATING
+1'-6"
TOILET
TOILET
CAP CLUB
MEDIA ROOM
CATERING KITCHEN
MAINT. WK SHOP
COMM RM
COMM RM
COMM RM
COMM RM
C.U.P.

LOWER LEVEL


VENDING SITTING
VENDING SITTING
TOILET
TOILET
CAP CLUB
MEDI ROOM
CATERING KITCHEN
MAINT WK SHOP
COMM RM
COMM RM
COMM RM
COMM RM
C.U.P.

1ST FLOOR



1ST FLOOR



1ST FLOOR



1ST FLOOR


15,000 NASF
3,500 NASF
12,600 NASF
8,600 NASF
10,500 NASF
11,000 NASF
ELEC
ELEC
IT
HK
A
B
MECH
E

2ND FLOOR



2ND FLOOR



2ND FLOOR



2ND FLOOR


15,000 NASF
12,600 NASF
12,600 NASF
IT
HK
Mech
E
2,500 NASF
2,500 NASF
7,500 NASF
8,000 NASF

3RD FLOOR



3RD FLOOR



3RD FLOOR



3RD FLOOR


18,500 NASF
12,600 NASF
12,600 NASF
IT
HK
MEP
E
2,100 NASF
2,100 NASF
7,500 NASF
8,000 NASF

4TH FLOOR



4TH FLOOR



4TH FLOOR



4TH FLOOR


11,500 NASF
12,600 NASF
12,600 NASF
7,500 NASF
8,000 NASF
1,700 NASF
1,700 NASF
CT
GEN
ADJ
IT
HK
MECH
E

Pioneer Site Update

- Soils
- Demolition
- Design

HDR
PDP
PLAN

Systems Update

- Security Systems
- Audio Visual Systems

HDR
PDP
PLAN

Next Steps

- Oversight Committee
- On-Site Investigations
- Space Planning
- Schedule Reconciliation

HDR
PDP
PLAN

Thank You!